

#### Comal County OFFICE OF COMAL COUNTY ENGINEER

### License to Operate On-Site Sewage Treatment and Disposal Facility

Issued This Date:

02/21/2019

Permit Number: 108167

Location Description:

1012 ROADRUNNER LN CANYON LAKE, TX 78133

Subdivision:

Canyon Lake Acres

Unit:

Lot:

269, 270, Part of 267, & Part of 268

Block: Acreage:

Type of System:

Aerobic

Surface Irrigation

Issued to:

Texas Hill Country Cottages, LLC

This license is authorization for the owner to operate and maintain a private facility at the location described in accordance to the rules and regulations for on-site sewerage facilities of Comal County, Texas, and the Texas Commission on Environmental Quality.

The license grants permission to operate the facility. It does not guarantee successful operation. It is the responsibility of the owner to maintain and operate the facility in a satisfactory manner.

Alterations to this permit including, but not limited to:

- Increase in the square feet of living area
- Increase in the number of bedrooms
- A change of use (i.e. residential to commercial)
- Relocation of system components (including the relocation of spray heads)
- Installation of landscaping
- Adding new structures to the system

may require a new permit. It is the responsibility of the owner to apply for a new permit, if applicable.

Inspection and licensing of a facility indicates only that the facility meets certain minimum requirements. It does not impede any governmental entity in taking the proper steps to prevent or control pollution, to abate nuisance, or to protect the public health.

This license to operate is valid for an indefinite period. The holder may transfer it to a succeeding owner, provided the facility has not been remodeled and is functioning properly.

Licensing Authority

Comal County Environmental Health

ENVIRONMENTAL HEALTH INSPECTOR

OS 0025599

Installer Name: Randy Ba	tery		OSSF Installer #: 05000		10.110	
1st inspection Date: 2.13		2nd Inspection Da		pector Name:	ike T.	
Permit#: 108147			Address: 1012 Roadunne	nho-Ch	acres	_
tion SITE AND SOLL COMBINIONS & SETHACK DISTANCES Size and Soll Constitions Consistent with Submitted Planning Materials	Inscent	Chations  285.57(a)  285.90(b)(3)(A)(iv)  285.30(b)(1)(A)(v)  285.30(b)(1)(A)(iii)  285.30(b)(3)(A)(ii)  285.30(b)(4)(A)(ii)		1st Insp.  2   3   9	2/2/	1
STEANBSOLCONDITIONS & SERVICE OF SERVICES SERVICE Detaines Meet Minimum Standards		285.93(10) 285.90(b)(4) 285.31(d)				A Company of the Parket
SEWER PIPE Proper Type Pipe from Structure to Disposal System (Cast Iron, Ductile Iron, Sch. 40, SDR 26)	<b>V</b>	285.32(a)(1)				
SEWER PIPE Slope from the Sewer to the Tank at least 1/8 Inch Per Foot	1	285.32(a)(3)				
SEWER PIPE Two Way Sanitary - Type Cleanout Properly Installed (Add. C/O Every 100' &/or 90 degree bends)	<b>J</b>	285.32(a)(5)				
PRETREATMENT installed (if required) TCRS Approved Hist PRETREATMENT action (in the Minimum Requirements.		285 37(b)(1)(c) 285 32(b)(1)(c)(iii) 285 32(b)(1)(c)(iii) 285 32(b)(1)(c) 285 32(b)(1)(c)(i) 285 32(b)(1)(c)(i) 285 32(b)(1)(c)(i) 285 32(b)(1)(c) 285 32(b)(1)(c) 285 32(b)(1)(c) 285 32(b)(1)(c) 285 32(b)(1)(c) 285 32(b)(1)(c) 285 32(b)(1)(c)(i) 285 32(b)(1)(c)(i) 285 32(b)(1)(c)(i) 285 32(b)(1)(c)(i)				
PRETREATMENT Grease Interceptors if required for commercial		285.34(d)				

SH 2/13/19 tank set, level operational ready for cover

MT2/21/19 Covered.

dq.		Anwser	Citations	tiotes	150 11	nsp.	2nd Insp.	3rd Insp.
	SEPTIC TANK Tank(s) Clearly Marked SEPTIC TANK If SingleTank, 2 Compartments Provided with Baffle SEPTIC TANK Inlet Flowline Greater than 3° and "T" Provided on Inlet and Outlet SEPTIC TANK Septic Tank(s) Meet Minimum Requirements		285.32(b)(1)(E) 285.91(2) 285.32(b)(1)(E)(iii) 285.32(b)(1)(E)(iii) 285.32(b)(1)(E)(ii)(II) 285.32(b)(1)(E)(ii)(II) 285.32(b)(1)(E)(ii) 285.32(b)(1)(C)(ii) 285.32(b)(1)(C)(ii) 285.32(b)(1)(C)(ii) 285.32(b)(1)(B) 285.32(b)(1)(E)(iv)		2/13	3/19		2/21/)
	ALL TANKS Installed on 4 <sup>th</sup> Sand Cushion/ Proper Backfill Used	7	285.32(b)(1)(F) 285.32(b)(1)(G) 285.34(b)					
	SEPTIC TANK Inspection / Clean Out Port & Risers Provided on Tanks Buried Greater than 12" Sealed and Capped	J	285.38(d)					
	SEPTIC TANK Secondary restraint system provided SEPTIC TANK Riser permanently fastened to lid or cast into tank SEPTIC TANK Riser cap protected against unauthorized intrusions	1	285.38(d) 285.38(e)					
	SEPTIC TANK Tank Volume Installed	1						
3	PUMP TANK Volume Installed	1						1
	ARAGINE THEAT WENT UNITS IN March of			Pao -				
5	AEROBIC TREATMENT UNIT Mahulacture AEROBIC ERFATMENT UNIT Model Number	T.		Solain Un				
	DISPOSAL SYSTEM Absorptive		285.33(a)(4) 285.33(a)(1) 285.33(a)(2) 285.33(a)(3)			400		
6	DISPOSAL SYSTEM Leaching Chamber		285.33(a)(1) 285.33(a)(3) 285.33(a)(4) 285.33(a)(2)					
18	DISPOSAL SYSTEM Evapo- transpirative		285.33(a)(3) 285.33(a)(4) 285.33(a)(1) 285.33(a)(2)					

No.	Description	Anwaer	Citations	Notes		1st insp.	2nd insp.	3rd Insp.
9	OSPOSAL SYSTEM Origination		285.33(a)(1) 285.35(a)(3) 285.35(a)(4) 285.33(a)(2)					
- 1	DISPOSAL SYSTEM Soil Substitution		285.33(d)(4)					
	DISPOSAL SYSTEM Fumped Effluent		285.33(a)(4) 285.33(a)(3) 285.33(a)(1)					
	DISPOSAL SYSTEM Gravelless Pipe		285.33(a)(3) 285.33(a)(2) 285.33(a)(4) 285.33(a)(1)					
	DISPOSAL SYSTEM Mound		285,33(a)(3) 285,83(a)(1) 285,83(a)(2) 285,33(a)(4)					
3	DISPOSAL SYSTEM Other (describe) (Approved Design)		285.33(d)(6) 285.33(c)(4)					
5	DRAINFIELD Absorptive Drainline 3* PVC 6**4* PVC DRAINFIELD Area Installed				And the second s		The second secon	
6	DRAINFELD Level to within 1 inch per 25 feet and within 3 inches over entire excivation	angenericke von	285.33(b)(1)(A)(v)					
7	DRAINFIELD Excavation Wight DRAINFIELD Excavition Depth DIAINFIELD Excavition Separation DiaInfield Depth of POORS Heris DRAINFIELD Type of Portous Media						The second secon	
8	ORAINHELD: tipe and (graye)	9. <u>A</u>					1	
30	Geotertile Fabric in Place  DRAINFIELD Les ching Chambers  DRAINFIELD Chambers * Open  End Plates w/Splash Plate, Inspection Poir & Closed Red  Naties in Place (pe) Instruction of Special  Instruction of Special		285-33(b)(1)(E) 285-33(c)(2)					
31	LOW PRESSURE DISPOSAL SYSTEM Adequate Trench Length & Width, and Adequate Separation Distance between Trenches		285.33(d)(1)(C)(i)					

No	New Hollon	Anweig	Citations	Notes	. 44	1st insp.	2nd Insp.	3rd Insp.
32	EFFLUENT DISPOSAL SYSTEM Utilized Only by Single Family Dwelling EFFLUENT DISPOSAL SYSTEM Topographic Slopes < 2.0% EFFLUENT DISPOSAL SYSTEM Adequate Length of Drain Field ( 1000 Linear ft. for 2 bedrooms or Less & an additional 400 ft. for each additional bedroom ) EFFLUENT DISPOSAL SYSTEM Lateral Depth of 18 inches to 3 ft. & Vertical Separation of 1ft on bottom and 2 ft. to restrictive horizon and ground water respectfully EFFLUENT DISPOSAL SYSTEM Lateral Drain Pipe (1.25 - 1.5" dia.) & Pipe Holes ( 3/16 - 1/4" dia. Hole Size ) 5 ft. Apart		285.33(b)(3)(A) 285.33(b)(3)(B) 285.33(b)(3)(B) 285.91(13) 285.33(b)(3)(D) 285.33(b)(3)(F)					
33	AEROBIC TREATMENT UNITES AEROBIC UNIT INSTANTO ACCORDING LO Approve d'Guldelines		285.32(cj[1)					
	PEONIC REPORTED FOR BUILD FOR SELECTION OF POOR							
	Provided AERORIC TREAT MENT UNIT Pice Transparently fastened to lid or distanto tank— AERORIC TREATMENT UNIT Ricer							
34	cationotected as in a unauthorized institutions . APROBLET READMENT ON IT.							
35	Colorrator Property installed with Colorine Tables in Place Pump Tank an	W.				श्रेष्ठाप		2/2/19
	approved concrete tank or other acceptable materials & construction PUMP TANK Sampling Port Provided in the Treated Effluent							
36	Line PUMP TANK Check Valve and/or Anti- Siphon Device Present When Required PUMP TANK Audible and Visual High Water Alarm Installed on Separate Circuit From Pump							
	PUMP TANK Inspection/Clean Out Port & Risers Provided PUMP TANK Secondary restraint system provided PUMP TANK Riser permanently fastened to lid or cast into tank PUMP TANK Riser cap protected against unauthorized intrusions							
37	PUMP TANK Secondary restraint system provided							

PUMP TANK Electrical	1					
Connections in Approved		13	112	10	2/21/19	
39 Junction Boxes / Wiring Buried		×	13	17	-1-111	

No,	Description	Aswises	Citations	Notes	A: -	1st insp.	2nd Inspi	3rd Insp.
40	APPLICATION AREA Distribution rips, Vitting, Sprinker Heads & Valve Covers Color Coded Purple?		285.33(d)(2)(G)(III)(II)285.3 3(d)(2)(G)(III)(III)285.33(d)( 2)(G)(v) 285.33(d)(2)(G)(III) 285.33(d)(2)(G)(IV) 285.33(d)(2)(G)(II) 285.33(d)(2)(G)(III)(II) 285.33(d)(2)(G)(III)(II)			2/5l 9		2.teilig
41	APPLICATION SIE ALLOW Angle Nozeles Used / Prescin Ale as required APPLICATION AREA Acceptable Sires, nothing within 10 th of sprinkler heads? APPLICATION AREA The Lundwape Plant's at Dellaried	V	285.33(d)(2)(G)(f) 285.33(d)(2)(A) 285.33(d)(2)(F)					
42	APPRICATION ALEXANDER SE SILEC			28 28275	944			
43	PUMP TANK Meets Minimum Reserve Capacity Requirements				1			•
44	PUMP TANK Material Type & Manufacturer							
45	PUMP TANK Type/Size of Pump Installed							

Installer Name: Randy Batery  1st Inspection Date: 2.13.19	OSSF In	staller #: 050007881
1st Inspection Date: 2.13.19	2nd Inspection Date:	3rd Inspection Date:
Inspector Name: A. Helmke	Inspector Name:	Inspector Name:
Permit#: 108147	Address:	012 Roadrunner LN - Ch acres
p, Description Anwser	Citations	Notes 1st insp. 2nd insp. 3rd insp.

	Permit#: 108147		***************************************	Address: 1012 Readtunner 1	-N -	<u> </u>	ucres	
No.	Description	Anwser	Citations	Notes	1st ins		2nd Insp.	3rd Insp.
1	SITE AND SOIL CONDITIONS & SETBACK DISTANCES Site and Soil Conditions Consistent with Submitted Planning Materials		285.31(a) 285.30(b)(1)(A)(iv) 285.30(b)(1)(A)(ii) 285.30(b)(1)(A)(iii) 285.30(b)(1)(A)(ii) 285.30(b)(1)(A)(i)		<u>ત્ર</u> ાક્ષ	19	ine	
2	SITE AND SOIL CONDITIONS & SETBACK DISTANCES Setback Distances Meet Minimum Standards		285.91(10) 285.30(b)(4) 285.31(d)					
3	SEWER PIPE Proper Type Pipe from Structure to Disposal System (Cast Iron, Ductile Iron, Sch. 40, SDR 26)	$\checkmark$	285.32(a)(1)					
4	SEWER PIPE Slope from the Sewer to the Tank at least 1/8 Inch Per Foot	1	285.32(a)(3)					
	SEWER PIPE Two Way Sanitary - Type Cleanout Properly Installed (Add. C/O Every 100' &/or 90 degree bends)	<b>\sqrt</b>	285.32(a)(5)					
5	PRETREATMENT Installed (if required) TCEQ Approved List PRETREATMENT Septic Tank(s) Meet Minimum Requirements		285.32(b)(1)(G)285.32(b)(1 (E)(iii) 285.32(b)(1)(E)(iv) 285.32(b)(1)(F) 285.32(b)(1)(C)(i) 285.32(b)(1)(C)(ii) 285.32(b)(1)(C)(ii) 285.32(b)(1)(D) 285.32(b)(1)(E) 285.32(b)(1)(E) 285.32(b)(1)(E)(ii)(ii) 285.32(b)(1)(E)(ii)(ii) 285.32(b)(1)(E)(ii)(ii)					
7	PRETREATMENT Grease Interceptors if required for commercial		285.34(d)					

SH 2/13/19 tank set, level operational ready for cover

20


No.	Description	Anwser	Citations	Notes	1st la	isp.	2nd Insp.	3rd Insp.
-	SEPTIC TANK Tank(s) Clearly					4.0.00.00		
	Marked SEPTIC TANK If		285.32(b)(1)(E)					
	SingleTank, 2		285.91(2)		ļ			
	Compartments Provided with		285.32(b)(1)(F)					·
	Baffle SEPTIC TANK Inlet Flowline		285.32(b)(1)(E)(iii)					
	Greater than		285.32(b)(1)(E)(ii)(Ii)					
	3" and " T " Provided on Inlet and		285.32(b)(1)(E)(ii)(I)		1 ,			
	Outlet		285.32(b)(1)(E)(i)		\	1.0		
	SEPTIC TANK Septic Tank(s) Meet		285.32(b)(1)(D)		1/1/2	$\gamma \gamma \gamma \gamma$		
1			285.32(b)(1)(C)(ii)		10/10	1.		
	Minimum Requirements		285.32(b)(1)(C)(i)		' '	( `	i	
		\ \	285.32(b)(1)(B)					
			285.32(b)(1)(A)					
			285.32(b)(1)(E)(iv)					
8								
	ALL TANKS Installed on 4" Sand							
	Cushion/ Proper Backfill Used	,	285.32(b)(1)(F)					
		$\checkmark$	285.32(b)(1)(G)					
9			285.34(b)					
3	SEPTIC TANK Inspection / Clean							
	Out Port & Risers Provided on	,						
	Tanks Buried Greater than 12"	/	205.20/4/		1			
	Sealed and Capped	$\sim$	285.38(d)					
10	SEPTIC TANK Secondary restraint				-			
	system provided							
	SEPTIC TANK Riser permanently	1						
1	fastened to lid or cast into tank	$\sqrt{}$			1 \			
	SEPTIC TANK Riser cap protected	<b>V</b>			1			
	against unauthorized intrusions		285.38(d)		1 1			
	oganist anouthorized mir asions		285.38(e)					
11		/						
	SEPTIC TANK Tank Volume Installed	$\sqrt{}$						
12								
	PUMP TANK Volume Installed					-		
13	AEROBIC TREATMENT UNIT Size	_			\$30000000000000000000000000000000000000	7///****		
	Installed				I. I	- 4		
		V		000	land I			
14		100					Total Control	
	AEROBIC TREATMENT UNIT	200	40.00			1, 4, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,		0.00
	Manufacturer			Ch. W.	1	7.5		
	AEROBIC TREATMENT UNIT			Ook and will	1			4 5
	Model	N.		Sofan Oir			100	- 1
15	Number	200 200						100
	DISPOSAL SYSTEM Absorptive		285.33(a)(4)					
1	·		285.33(a)(1)					
			285.33(a)(2)		Ì			
16			285.33(a)(3)					
	DISPOSAL SYSTEM Leaching		285.33(a)(1)					
	Chamber		285.33(a)(3)					
			285.33(a)(4)					
17			285.33(a)(2)					
	DISPOSAL SYSTEM Evapo-		285.33(a)(3)					
	transpirative		285.33(a)(4)					
			285.33(a)(1)					
18			285.33(a)(2)					
	·	<u> </u>	<u> </u>					

No.	Description	Anwser	Citations	Notes	1st Insp.	2nd Insp.	3rd Insp.
19	DISPOSAL SYSTEM Drip Trigation		285.33(a)(1) 285.33(a)(3) 285.33(a)(4) 285.33(a)(2)			The Second of th	
20	DISPOSAL SYSTEM Soil Substitution		285.33(d)(4)				
21	DISPOSAL SYSTEM Pumped Effluent	2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 -	285,33(a)(4) 285.33(a)(3) 285.33(a)(1)				
22	DISPOSAL SYSTEM Gravelless Pipe		285.33(a)(3) 285.33(a)(2) 285.33(a)(4) 285.33(a)(1)				
23	DISPOSAL SYSTEM Mound		285.33(a)(3) 285.33(a)(1) 285.33(a)(2) 285.33(a)(4)				
24	DISPOSAL SYSTEM Other (describe) (Approved Design)		285.33(d)(6) 285.33(c)(4)				
25	DRAINFIELD Absorptive Drainline 3" PVC or 4" PVC						
26	DRAINFIELD Area Installed		The second secon				
27	DRAINFIELD Level to within 1 inch per 25 feet and within 3 inches over entire excavation		285.33(b)(1)(A)(v)				
28	DRAINFIELD Excavation Width DRAINFIELD Excavation Depth DRAINFIELD Excavation Separation DRAINFIELD Depth of Porous Media DRAINFIELD Type of Porous Media						
29	DRAINFIELD Pipe and Gravel - Geotextile Fabric in Place	ANNE.	285.33(b)(1)(E)				
30	DRAINFIELD Leaching Chambers DRAINFIELD Chambers - Open End Plates w/Splash Plate, Inspection Port & Closed End Plates in Place (per manufacturers spec.)		285.33(c)(2)				
31	LOW PRESSURE DISPOSAL SYSTEM Adequate Trench Length & Width, and Adequate Separation Distance between Trenches		285.33(d)(1)(C)(i)				

LUENT DISPOSAL SYSTEM Utilized y by Single Family Dwelling LUENT DISPOSAL SYSTEM lographic Slopes 0% EFFLUENT DISPOSAL SYSTEM equate Length of Drain Field (1000 ear ft. for 2 bedrooms or Less in additional 400 ft. for each litional bedroom) LUENT DISPOSAL SYSTEM Lateral oth of 18 inches to 3 ft. & Vertical laration of 1ft on bottom and 2 ft. to trictive horizon and ground water pectfully		285.33(b)(3)(A) 285.33(b)(3)(A) 285.33(b)(3)(B) 285.91(13)				
LUENT DISPOSAL SYSTEM Lateral in Pipe (1.25 - 1.5" dia.) & Pipe es (3/16 - 1/4" dia. Hole Size ) 5 ft. irt		285.33(b)(3)(D) 285.33(b)(3)(F)				
ROBIC TREATMENT UNIT IS robic Unit installed According Approved Guidelines.	14 (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	285.32(c)(1)				
ROBIC TREATMENT UNIT pection/Clean Out Port & ers Provided ROBIC TREATMENT UNIT condary restraint system ovided AEROBIC TREATMENT IT Riser permanently fastened id or cast into tank ROBIC TREATMENT UNIT Riser protected against authorized intrusions						
ROBIC TREATMENT UNIT formator Properly Installed th Chlorine Tablets in Place.		197 <b>4</b>		2/13/19		
MP TANK is the Pump Tank an proved concrete tank or other peptable materials & astruction MP TANK Sampling Port pointed in the Treated Effluent e MP TANK Check Valve and/or ti- Siphon Device Present are Required MP TANK Audible and Visual the Water Alarm Installed on parate Circuit From Pump						
t Port & Risers Provided MP TANK Secondary restraint tem provided MP TANK Riser permanently	,					
分配 へつぎょう べきんけい たけつ うきんけん	AP TANK Check Valve and/ori-Siphon Device Present en Required MP TANK Audible and Visual Water Alarm Installed on arate Circuit From Pump MP TANK Inspection/Clean POTANK Inspection/Clean POTANK Secondary restraint em provided MP TANK Secondary restraint em provided MP TANK Secondary restraint em provided MP TANK Riser permanently ened to lid or cast into tank	AP TANK Inspection/Clean Port & Risers Provided MP TANK Inspection/Clean Port & Risers Provided MP TANK Inspection/Clean Port & Risers Provided MP TANK Secondary restraint em provided MP TANK Inspection/Clean Port & Risers Provided MP TANK Secondary restraint em provided MP TANK Riser permanently ened to lid or cast into tank	ACRIOTINE Tablets in Place.  AP TANK Is the Pump Tank an roved concrete tank or other eptable materials & struction  AP TANK Sampling Port wided in the Treated Effluent  AP TANK Check Valve and/or in Siphon Device Present en Required  AP TANK Audible and Visual in Water Alarm Installed on earate Circuit From Pump  AP TANK Inspection/Clean  Port & Risers Provided  AP TANK Secondary restraint em provided  AP TANK Riser permanently ened to lid or cast into tank	Armator Properly Installed Chlorine Tablets in Place.  AP TANK Is the Pump Tank an roved concrete tank or other eptable materials & struction  AP TANK Sampling Port yided in the Treated Effluent  AP TANK Check Valve and/or is Siphon Device Present en Required  AP TANK Audible and Visual in Water Alarm Installed on arate Circuit From Pump  AP TANK Inspection/Clean  Port & Risers Provided  AP TANK Secondary restraint em provided  AP TANK Riser permanently ened to lid or cast into tank	AP TANK Audible and Visual on Water Alarm Installed on Water Alarm Installed on AP TANK Inspection/Clean Port & Risers Provided AP TANK Secondary restraint em provided AP TANK Riser permanently ened to lid or cast into tank	AP TANK Audible and Visual on Water Alarm Installed on Water Alarm Installed on Water Alarm Installed on arate Circuit From Pump  AP TANK Inspection/Clean POTANK Inspection/Clean POTANK Secondary restraint em provided AP TANK Riser permanently

	PUMP TANK Electrical	1			,	
	Connections in Approved			1 13	1.0	
39	Junction Boxes / Wiring Buried	V		2 13	119	

No.	Description	Anwser	Citations	Notes	1st Insp.	2nd Insp.	3rd Insp.
	APPLICATION AREA Distribution Pipe, Fitting, Sprinkler Heads & Valve Covers Color Coded Purple?	√.	285.33(d)(2)(G)(iii)(II)285.3 3(d)(2)(G)(iii)(III)285.33(d)( 2)(G)(v) - 285.33(d)(2)(G)(iii) 285.33(d)(2)(G)(iv) 285.33(d)(2)(G)(i) 285.33(d)(2)(G)(ii) 285.33(d)(2)(G)(iii)(I)		2/3/19		
41	APPLICATION AREA Low Angle Nozzles Used / Pressure is as required APPLICATION AREA Acceptable Area, nothing within 10 ft of sprinkler heads? APPLICATION AREA The Landscape Plan is as Designed	7	285.33(d)(2)(G)(j) 285.33(d)(2)(A) 285.33(d)(2)(F)				
42	APPLICATION AREA Area Installed	1	3.75	2@ 2827 sqff			
	PUMP TANK Meets Minimum Reserve Capacity Requirements						
43							,
44	PUMP TANK Material Type & Manufacturer						
45	PUMP TANK Type/Size of Pump Installed						



# Permit of Authorization to Construct an On-Site Sewage Facility Permit Valid For One Year From Date Issued

Permit Number: 108167

Issued This Date: 01/17/2019

This permit is hereby given to: Texas Hill Country Cottages, LLC

To start construction of a private, on-site sewage facility located at:

1012 ROADRUNNER LN CANYON LAKE, TX 78133

Subdivision: Canyon Lake Acres

Unit: 2

Lot: 269, 270, Part of 267, & Part of 268

Block:

Acreage:

#### APPROVED MINIMUM SIZES AS PER ATTACHED DESIGN

Type of System: Aerobic

Surface Irrigation

This permit gives permission for the construction of the above referenced on-site facility to commence. Installation must be completed by an installer holding a valid registration card from the Texas Commission on Environmental Quality (TCEQ). Installation and inspection must comply with current TCEQ and Comal County requirements.

Call (830) 608-2090 to schedule inspections.

### OSSF DEVELOPMENT APPLICATION CHECKLIST

Staff will complete shaded
items Date Received initials

Permit Number

Instructions:

Place a check mark next to all items that apply. For items that do not apply, place "N/A". This OSSF Development Application Checklist must accompany the completed application.

#### **OSSF Permit**

Completed Application for Permit for Authorization to Construct an On-Site Sewage Facility and License to Operate

X Site/Soil Evaluation Completed by a Certified Site Evaluator or a Professional Engineer

Planning Materials of the OSSF as Required by the TCEQ Rules for OSSF Chapter 285. Planning Materials shall consist of a scaled design and all system specifications.

Required Permit Fee

Copy of Recorded Deed

SEP 25 2018

X Surface Application/Aerobic Treatment System

X Recorded Certification of OSSF Requiring Maintenance/Affidavit to the Public

X Signed Maintenance Contract with Effective Date as Issuance of License to Operate

I affirm that I have provided all information required for my OSSF Development Application and that this application constitutes a completed OSSF Development Application.

Signature of Applicant

09/21/18 Date

\_COMPLETE APPLICATION

Check No.\_\_\_\_ Receipt No. \_\_\_\_

INCOMPLETE APPLICATION

(Missing Items Circled, Application Refused)

### \* \* \* COMAL COUNTY OFFICE OF ENVIRONMENTAL HEALTH

### **REVISED** 9:44 am, Jan 15, 2019

Revised July 2018

APPLICATION FOR PERMIT FOR AUTHORIZATION TO CONSTRUCT AN ON-SITE SEWAGE FACILITY AND LICENSE TO OPERATE

	UN-SITE SEWAGE FACILITY	Y AND LICENSE TO	OPERATE LA QII.
DateAt	ugust 21, 2018		Permit # 108167
Owner Name	TEXAS HILL COUNTRY COTTAGES, LLC	Agent Name	GREG W. JOHNSON, P.E.
Mailing Address	824 SHELLY DRIVE	Agent Address	170 HOLLOW OAK
City, State, Zip	CANYON LAKE TEXAS 78133	City, State, Zip	NEW BRAUNFELS, TX 78132
Phone#	713-824-2650	Phone #	(830) 905-2778
Email	jay1949@gvtc.com	Email	gregjohnsonpe@yahoo.com
All corresponden	ce should be sent to: Owner Agent	☐ Both	Method: Mail Email
Subdivision Nam		ase/Section 2	Lot 267, <b>2</b> 68, 269, 270 Block
Acreage/Legal _	0.382 Ac		
Street Name/Add	dress 1012 ROADRUNNER LANE	City C	ANYON LAKE Zip 78133
Number of Indicate So Indicate	Residential Instruction (House, Mobile, RV, Etc.)  Bedrooms 2  Q Ft of Living Area 1200  or Institutional Facility rials must show adequate land area for doubling the cility actories, Churches, Schools, Parks, Etc Indits, Lounges, Theaters - Indicate Number of Stel, Hospital, Nursing Home - Indicate Number	he required land need licate Number Of Od Seats	ccupants
Travel Tra	iler/RV Parks - Indicate Number of Spaces _		
Miscellane	ous		
Is any portion of	of Construction: \$\frac{185,000}{the proposed OSSF located in the United States (if yes, owner must provide approval from USACE for		
Source of Water	Public Private Well		
Are Water Saving	g Devices Being Utilized Within the Residence	e? X Yes No	
-Authorization is her site/soil evaluation -Lalso understand the by the Comal Coun	cation, I certify that: ication and all additional information submitted does no reby given to the permitting authority and designated ag and inspection of private sewage facilities. at a permit of authorization to construct will not be issue ty Flood Damage Prevention Order. ent to the online posting/public release of my e-mail add	gents to enter upon the a ed until the Floodplain A	above described property for the purpose of dministrator has performed the reviews required
Signature of Owne		Date	Page I of 2

195 David Jonas Dr., New Braunfeis, Texas 78132-3760 (830) 608-2090 Fax (830) 608-2078

### \* \* \* COMAL COUNTY OFFICE OF ENVIRONMENTAL HEALTH \*

# APPLICATION FOR PERMIT FOR AUTHORIZATION TO CONSTRUCT AN ON-SITE SEWAGE FACILITY AND LICENSE TO OPERATE

**REVISED** 9:44 am, Jan 15, 2019

Planning Materials & Site Evaluation as Required Completed By GREG W. JOHNSON, P.E.
System Description PROPRIETARY; AEROBIC TREATMENT AND SURFACE IRRIGATION
Size of Septic System Required Based on Planning Materials & Soil Evaluation
Tank Size(s) (Gallons)SOLAR AIR SA600 LPAbsorption/Application Area (Sq Ft)2827
Gallons Per Day (As Per TCEQ Table III) 180  (Sites generating more than 5000 gallons per day are required to obtain a permit through TCEQ)
Is the property located over the Edwards Recharge Zone?  Yes No  (If yes, the planning materials must be completed by a Registered Sanitarian (R.S.) or Professional Engineer (P.E.))
Is there an existing TCEQ approved WPAP for the property?  Yes No
(if yes, the R. S. or P. E. shall certify that the OSSF design complies with all provisions of the existing WPAP.)
If there is no existing WPAP, does the proposed development activity require a TCEQ approved WPAP? Yes No
(If yes, the R.S. or P. E. shall certify that the OSSF design will comply with all provisions of the proposed WPAP. A Permit to Construct will not be issued for the proposed OSSF until the proposed WPAP has been approved by the appropriate regional office.)
Is the property located over the Edwards Contributing Zone? Yes No
Is there an existing TCEQ approval CZP for the property?  Yes  No
(if yes, the P.E. or R.S. shall certify that the OSSF design complies with all provisions of the existing CZP)
If there is no existing CZP, does the proposed development activity require a TCEQ approved CZP? Yes No (if yes, the P.E. or R.S. shall certify that the OSSF design will comply with all provisions of the proposed CZP. A Permit to construct will) not be issued for the proposed OSSF until the CZP has been approved by the appropriate regional office.)
Is this property within an incorporated city? Yes No
If yes, indicate the city:  GREG W. JOHNSON
FIRM #2585
By signing this application, I certify that:  The information provided above is true and correct to the heat of the legal date.
<ul> <li>The information provided above is true and correct to the best of my knowledge.</li> <li>I affirmatively consent to the online posting/public release of my e-mail address associated with this permit application, as applicable</li> </ul>
Soutomber 10, 2019
Signature of Designer Date Page 2 of 2

# AFFIDAVIT TO THE PUBLIC

THE COUNTY OF COMAL §

STATE OF TEXAS

who after being by me duly sy	worn, upon oath state that d being situated in Comal	they are the owner of record of the County, Texas, and being more p	nat certain
2 UNIT/PHASE/SECTION	(pr)(Pr)  BLOCK 267, 268, 269, 4 270 Le	OT CANYON LAKE ACRES	SUBDIVISION
IF NOT IN SUBDIVISION: 0.4	174 ACREAGE ALLOTS	270+269, + Remainder of Cot 260	8+267 SURVEY
	rties. These properties can	acility for the referenced propertie not be sold separately and must be juirement.	
JAY SETCHELL - MANAGER		September, 20_18.	
SWORN TO AND SUBSCI	RIBED BEFORE ME on	this 17 day of Septemb	<u>ec20_18</u> .
Notary Public Signatu	ure		
Wy Comm. Explices 05-20-2020  ALEX RUE Notary Public State of Texas State of Texas Alexan Comm. Explices 05-20-2020	FTEXAS 67096-9 es 05-20-2020	Filed and Recorded Official Public Re Bobbie Koepp, Coun Comal County Jexa 09/25/2018 11:27:4 TERRI 2 Page(s) 201806037677	ty Clerk s



This page has been added to comply with the statutory requirement that the clerk shall stamp the recording information at the bottom of the last page.

This page becomes part of the document identified by the file clerk number affixed on preceding pages.

Filed and Recorded
Official Public Records
Bobbie Koepp, County Clerk
Comal County Texas
10/29/2018 11:54:42 AM
TERRI 4 Page(s)
201806042036

Bobbie Koepp

### RECEIVED

By rabsah at 3:59 pm, May 03, 2019

# **GLEAR CHUICE SEPTIC SERVICES**

Contract Holder: Texas Hill Country Cottages Address: 1012 Roadrunner, Canyon Lake, Tx 78133 Permit: 108167 Lot:267-270Subdivision: Canyon Lake AcresCounty: ComalPhone:713-824-2650Email: Jay1949@gvtc.comSystem Type: Solar Aire-Spray-600 GPDManufacturer service notes: Compressor/ Liquid Chlorinator

### **Initial Two-Year Service Agreement**

The start date of the six-time visit service contract shall begin the date the License to operate (LTO) is issued. This contract will be in effect FROM: February 21, 2019 TO: February 21, 2021 and will provide the following:

- 1. An inspection/service call every four months which will include: inspection, adjustments and servicing of the mechanical and electrical components as necessary to ensure that the system functions correctly.
- 2. An effluent inspection will consist of a visual check for color, turbidity, scum layer in the clarifier and an examination for odors.
- 3. The property owner is responsible for purchasing and keeping chlorine in the chlorinator (if applicable). If the chlorine test reveals no chlorine in the system, the property owner will be notified and may incur an additional cost.
- 4. If any incorrect operation is observed the property owner will be contacted immediately of the conditions and a solution must be met at that time or more charges may apply.
- 5. All parts, warranty or non-warranty, freight charges, labor or service calls that have not been paid for, remain the property of CLEAR CHOICE SERVICES and will result in the repossession of parts before end of contract date.
- 6. The response time to a service call by the Contract Holder regarding concerns of the system will be within 48 hours from the time received. (phone contact is an acceptable response)
- 7. The signing of this Service Agreement authorizes Clear Choice Septic Services to enter the property to complete all terms of this contract.

Clear Choice Septic Services will complete service of the septic system according to state and manufacturer regulations and the designs approved by the state. Contract holder will be responsible for service calls, labor and shipping costs on any parts under Warranty or exchanged during Warranty, additional fees may apply. All other components will be according to Manufacturer's Warranty and specification.

Attention: Clear Choice Septic Service cannot control quality or amount of effluent that goes into this septic system, we cannot warranty how the system will operate. See manufacturer or installer instructions for suggestions on septic operation. This Service Agreement does not cover cost of service calls, Jahor, parts or materials that are required for service, failure to maintain access from restriction locked gates.

service calls, labor, parts or materials that are required for service, failure to maintain access from restricting vegetation, locked gates, unfriendly animals or electrical power to the system may result in a voided contract. Contract will not cover service calls such as sprinklers that are broken, leaking, stopped up or otherwise malfunctioning, sewage flows exceeding the hydraulic/organic design capabilities and the input of non-biodegradable materials (feminine products, sanitary wipes, solvents, grease, oil, paints, etc.), or any usage contrary to the requirements as advised by authorized Maintenance Provider. Inspection dates can be adjusted to allow inspection date under contract to take place of service call. Service call price may be adjusted at Clear Choice Septic Services discretion, without notice. This Contract does not include the pumping of tank or of any compartment of a tank or settlement of soil on or around any part of the system regardless of reason. Violations of this Contract also include: disconnecting the alarm, restricting ventilation to the aerator, overloading the system above its rated capacity; or flooding by external means. Ground water, rodent, insect or fire ant damage or any other form of unusual abuse is a violation. A renewal Service Contract should be activated 30 days before expiration of existing Contract. We will contact the Contract Holder prior to expiration of existing contract. As we take pleasure in servicing our active/retired military and senior community please have correct identification on hand when signing contract. (expired ID's are not valid) CLEAR CHOICE SEPTIC SERVICES has the right to refuse service to any party for any reason. Funds that have been paid for contract will be applied to any service calls and or labor. Remaining funds will be distributed at Clear Choices discretion. Contract holders will be notified 30 days before contract is terminated. The signing of this contract is an acknowledgment and agreement of all terms listed above.

	days before contract is terminated. The signing of this contract is an acknowledgment and agreement of all terms listed above.
	Serviced by: Clear Choice Septic Services, 1659 State Hwy 46 W Ste 115-200 New Braunfels, TX 78132
-	Phone: 830-624-5859
	Justin Trevino Maintenance Provider License # MP0002136
	Date:
/	Contract Holder Signature/Property Owner
-	MELOTE PARTY
ţ.,	Printed Name
	Justin Freuito Date: 2-28-19
	Authorized Maintenance Provider

**REVISED** 9:44 am, Jan 15, 2019

### Greg W. Johnson, P.E.

170 Hollow Oak New Braunfels, Texas 78132 830/905-2778

January 10, 2019

Comal County Office of Environmental Health 195 David Jonas Drive New Braunfels, Texas 78132-3760

RE: Septic Design #108167

1012 Road Runner Lane

Canyon Lake Acres, Unit 2, Lot 267(pt), 268 (pt), 269 & 270

Canyon Lake, TX 78133

Texas Hill Country Cottages, LLC

Ms. Ritzen/Hernandez,

Due to the lack of available application area it is necessary to have the setback from the property line to the spray at ten feet as required by TCEQ Chapter 285 rules Table X. I hereby request a variance to the twenty foot setback to property lines as required by Comal County Order and equivalent protection will be maintained by including a battery backup to the timer clock to assure sprayers to only spray during the predawn hours. In my professional opinion this variance will not pose a threat to the environment or public health.

If I can be of further assistance please contact me.

Respectfully yours,

Greg W. Johnson, P.E., F#2585

GREG W. JOHNSON

OFFICIAL STATE

OFFICIAL STAT



# ON-SITE SEWERAGE FACILITY SOIL EVALUATION REPORT INFORMATION

Date Soil Survey Performed: Sept	
	Pt
Site Location: CANYON LAKE ACI	RES, UNIT 2, LOTS 267, 269, 270 & 0.382 acres being part of LOT 268
Proposed Excavation Depth:	N/A

#### Requirements:

At least two soil excavations must be performed on the site, at opposite ends of the proposed disposal area. Locations of soil boring or dug pits must be shown on the site drawing. For subsurface disposal, soil evaluations must be performed to a depth of at least two feet below the

proposed excavation depth. For surface disposal, the surface horizon must be evaluated.

Describe each soil horizon and identify any restrictive features on the form. Indicate depths where features appear.

Depth (Feet)	Texture Class	Soil Texture	Gravel Analysis	Drainage (Mottles/ Water Table)	Restrictive Horizon	Observations
1 10"	Ш	CLAY LOAM	N/A	NONE OBSERVED	LIMESTONE @ 10"	BROWN
2						
3						
4						
5						

Depth (Feet)	Texture Class	Soil Texture	Gravel Analysis	Drainage (Mottles/ Water Table)	Restrictive Horizon	Observations
0	SAME		AS		ABOVE	
2						
3						
4						
5						

I certify that the findings of this report are based on my field observations and are accurate to the best of my ability,

Greg W. Johnson, P.E. 67587-F2585, S.E. 11561

9/07/13 Date

REVISED

OBST SOIL EVALUATION	V KET OKT INFORMATION	
Date: September 10, 2018		9:45 am, Jan 15, 20
Applicant Information:		
	Site Evaluator Information:	
Name: TEXAS HILL COUNTRY COTTAGES, LLC.	Name: Greg W. Johnson, P.E., R.S., S.	E. 11561
Address: 824 SHELLY DRIVE	Address: 170 Hollow Oak	
City: CANYON LAKE State: TEXAS	City: New Braunfels State	: Texas
Zip Code: 78133 Phone: (713) 824-2650	Zip Code: <u>78132</u> Phone & Fax (83)	0)905-2778
Property Location:	Installer Information:	
Lot BLOW Unit 2 Blk Subd. CANYON LAKE ACR		
Street Address: 1012 ROADRUNNER LANE	('omnany:	
City: Zip Code: 78133	Address:	Attended to the second of the
City: CANYON LAKE Zip Code: 78133 Additional Info.: LOTS 267, 269, 270 & 0.382 acres being p	part City: S	tate:
01 LO 1 208	Zip Code: Phone	dealers and the second
<b><u>Topography:</u></b> Slope within proposed disposal area:	6 %	
Presence of 100 yr. Flood Zone:	YESNO_X	
Existing or proposed water well in nearby area.	YESNO_X	
Presence of adjacent ponds, streams, water impoundments	YESNO_X	
Presence of upper water shed	YESNO_X	
Organized sewage service available to lot	YESNO_X	
Design Calculations for Aerobic Treatment with Spr	ay Irrigation:	
Commercial		
Q = GPD		
Residential Water conserving fixtures to be utilized? Ye	es X No	
Number of Bedrooms the septic system is sized for:	2 Total sq. ft. living area 1200	
Q gal/day = (Bedrooms +1) * 75 GPD - (20% reduction	for water conserving fixtures)	
Q = (2 +1)*75-(20%) =180	8	
Frash Tank Size 376 Gal.		
TCEQ Approved Aerobic Plant Size 600 G	J.P.D.	
	064 = 2813 sq. ft.	

2827 Application Area Utilized =

\_\_ sq. ft.

Pump Requirement 12 Gpm @ 41 Psi (Redjacket 0.5 HP 18 G.P.M. series or equivalent)

Dosing Cycle: \_\_\_\_\_ON DEMAND or \_\_\_X \_\_TIMED TO DOSE IN PREDAWN HOURS

Pump Tank Size = 18.75 Gal/inch. 778 Gal.

Reserve Requirement = 60 Gal. 1/3 day flow.

Alarms: Audible & Visual High Water Alarm & Visual Air Pump malfunction

With Chlorinator NSF/TCEQ APPROVED

SCH-40 or SDR-26 3" or 4" sewer line to tank

Two way cleanout

Pop-up rotary sprinkler heads w/ purple non-potable lids

1" Sch-40 PVC discharge manifold

APPLICATION AREA SHOULD BE SEEDED AND MAINTAINED WITH VEGETATION.


I HAVE PERFORMED A THOROUGH INVESTIGATION BEING A REGISTERED PROFESSIONAL ENGINEER AND SITE EVALUATOR IN ACCORDANCE WITH CHAPTER 285, SUBCHAPTER D, §285.30, & §285.40 (REGARDING RECHARGE FEATURES), TEXAS COMMISSION OF ENVIRONMENTAL QUALITY (EFFECTIVE DECEMBER 29, 2016)

OHNSON, P.E. F#002585 - S.E. 11561

FIRM #2585


NOTE:

NO OSSF SYSTEM CAN BE INSTALLED ON THE SAME PROPERTY AS THE SINGLE FAMILY DWELLING, DUE TO PLACEMENT OF HOUSE AND SIZE OF LOT. TEXAS HILL COUNTRY COTTAGES, LLC. OWNS ALL FOUR PROPERTIES.



**REVISED** 

4:17 pm, Feb 12, 2019







TEXAS HILL COUNTRY COTTAGES, LLC.						DR	DRAWN BY: EJS III		
STREET ADDRESS: 1012 ROAD RUNNER	LANE								
CANYON LAKE ACRES	UNIT/SECTION/PHASE:	2	BLOCK:	LOT:	267, 268 (I	Part of)	, 269 & 270		
PREPARED BY: GREG W. JOHNSON, P.	E. F#002585	SCALE:	1"=40'	DATE:	9/10/2018	REVISE	D: 2/11/2019		

### **TANK NOTES:**

Tanks must be set to allow a minimum of 1/8" per foot fall from the residence.

Tightlines to the tank shall be SCH-40 PVC.

A two way sanitary tee is required between residence and tank.


RECEIVED

SEP 25 2018

COUNTY ENGINEER


A minimum of 4" of sand, sandy loam, clay loam free of rock shall be placed under and around tanks

# ALL WIRING MUST BE IN COMPLIANCE WITH THE MOST RECENT NATIONAL ELECTRIC CODE




TYPICAL PUMP TANK CONFIGURATION SOLAR-AIR SA-600 LP 778 GAL PUMP TANK

07349A



County. Texas.





# Comal County

OFFICE OF COMAL COUNTY ENGINEER

February 28, 2018

Texas Hill Country Cottages, LLC 1012 Roadrunner Lane Canyon Lake, TX 78133

RE: Initial Two-Year Contract Expired/Invalid (OSSF Permit #108167)

#### Dear Homeowner:

Comal County Environmental Health records indicate an expired or invalid maintenance contract for the On-site Sewage Facility (OSSF) serving your residence. State Law requires that a maintenance contract shall be effective for two years from the date the OSSF is first used. If you currently have a valid maintenance contract, please supply this office with a copy to update our records.

The purpose of the maintenance contract is to assure the OSSF remains in satisfactory working condition. The Texas Commission on Environmental Quality (TCEQ) requires testing of the OSSF and your maintenance provider reports those results to this office.

Operating an OSSF without a valid maintenance contract violates Title 30 of the Texas Administrative Code Chapter 285.7(c)(2) and 285.7(C)(2)(b). If you need information regarding maintenance contracts or need information on how to locate a maintenance provider, contact this office.

Failure to contact this office within 14 days of receiving this letter will result in appropriate action being initiated by this department.

If you have any questions, please call (830) 608-2090.

Respectfully,

Sandra Hernandez

Asst. Environmental Health Coordinator Comal County Environmental Health

### Friday, February 22, 2019 at 7:08:03 AM Central Standard Time

Subject: License to Operate issued for Permit #108167

Date: Thursday, February 21, 2019 at 9:00:01 PM Central Standard Time

From: Comal County Engineers Office

To: info@aerobicservices.com

License To Operate Issued

Permit Number: 108167

Location: 1012 ROADRUNNER LN

Maintenance Provider: Aerobic Services of South Texas

Installer: Batey Construction

Please do not reply to this email

Contractecanceley

2-22-19

Batey Johnson 9-25-18



15188 FM 306 Canyon Lake, TX 7813 Phone (830)964-2365 Fax (830) 964-2639



#### Routine Maintenance and Inspection Agreement

#### General

This Work for Hire Agreement (hereinafter referred to as this "Agreement") is entered into by and between TEXAS HILL COUNTRY COTTAGES LLC (referred to as "Client") and Aerobic Services of South Texas (Thomas W. Hampton MP 349) (hereinafter referred to as "Contractor") located at 15188 FM 306, Texas 78133 (830) 964-2365. By this Agreement the Contractor agrees to render professional service, as described herein, and the Client agrees to fulfill the terms of this Agreement as described herein.

This contract will provide for all required inspections, testing and service for your Aerobic Treatment System. The policy will include the following:

- 1. 3 inspections a year/services calls (at least one every 4 months), for a total of 6 over the **two year period** including inspection, adjustment and servicing of the mechanical, electrical and other applicable component parts to ensure proper function. This includes inspecting control panel, air pumps, air filters, diffuser operation. Any alarm situation affecting the proper function of the Aerobic process will be address within a 48-hour time Frame. Repair work on non-warranty parts with the Aerobic process will be quoted before work is performed.
- 2. An effluent quality inspection consisting of a visual check for color, turbidity, seum overflow and examination for odors. A test for chlorine residual and pH will be taken and reported as necessary.
- 3. If any improper operation is observed, which cannot be corrected at the time of the service visit, you will be notified immediately in writing of the conditions and estimated date of correction.
- 4. The customer is responsible for the chlorine tablets; they must be filled before or during the service visit.
- 5. Any additional visits, inspections or sample collection required by specific Municipalities, Water/River Authorities, and County Agencies the TCEQ or any other authorized regulatory agency in your jurisdiction will be covered by this policy.

The Homeowners Manual must be strictly followed or warranties are subject to invalidation. Pumping of sludge build-up is not covered by this policy and will result in additional charges.

### ACCESS BY CONTRACTOR

The Contractor or anyone authorized by the Contractor may enter the property at reasonable times without prior notice for the purpose of the above described Services. The contractor may access the System components including the tanks by means of excavation for the purpose of evaluations if necessary. Soil Is to be replaced with the excavated material as best as possible.







Termination of Agreement

Either party may terminate this agreement within ten days written notice in the event of substantial failure to perform in accordance with its terms by the other party without fault of the terminating party. If this Agreement is so terminated, the Contractor will immediately notify the appropriate health authority of the termination.

Limit of Liability

In no event shall the Contractor be liable for indirect, consequential, incidental or punitive damages, whether in contract tort or any other theory. In no event shall the Contractor's liability for direct damages exceed the price for the services described in this Agreement.

Dispute Resolution

If a dispute between the Client and the Designer arises that cannot be settled in good faith negotiations then the parties shall choose a mutually acceptable arbitrator and shall share the cost of the arbitration services equally.

Entire Agreement

Model =

This Agreement contains the entire agreement of the parties, and there are no other promises or conditions in any other agreement either oral or written.

VOID nenforceable for any reason, the remaining If any provision of this Agreement shall be he a court and that any provision of this agreement is provisions shall continue to be valid and enfor invalid or unenforceable, but that by limiting such provision it would become valid and enforceable, then such provision shall be deemed to be written, construed, and enforced as so limited.

0.382Ac. Legal Description: CANYON LAKE ACRES, UNIT 2, LOT 267, 268, 269, & 270

Property Address: 1012 ROADRUNNER LANE HOME OWNER SERVICE PROVIDER TEXAS HILL COUNTRY COTTAGES LLC 824 SHELLY DRIVE 15188 FM 306 CANYON LAKE, TEXAS 78133 Canyon Lake, Texas 78133 Clay State City. State 713-824-2650 (830) 964 - 2365 Thomas Hampton signature of Home Dwner Signature of Service Provider and License # EXPIRED DATE INSTALLED EFFECTIVE DATE

The effective date of this initial maintenance contract shall be the date license to operate is issued.

Blower Panel Senal =




**REVISED** 


9:45 am, Jan 15, 2019

NOTE:

NO OSSF SYSTEM CAN BE INSTALLED ON THE SAME PROPERTY AS THE SINGLE FAMILY DWELLING, DUE TO PLACEMENT OF HOUSE AND SIZE OF LOT. TEXAS HILL COUNTRY COTTAGES, LLC. OWNS ALL FOUR PROPERTIES.









TEXAS HILL COUNTRY COTTAGES, LLC.						DRAWN BY: EJS III
STREET ADDRESS: 1012 ROAD RUNNER	LANE					
CANYON LAKE ACRES	UNIT/SECTION/PHASE:	2	BLOCK:	LOT:	267(pt), 268	(pt), 269 & 270
PREPARED BY: GREG W. JOHNSON, P.I	E. F#002585	SCALE:	1''=40'	DATE:	9/10/2018	REVISED:

# AVIT TO THE PUBLIC **VOID**


THE COUNTY OF COMAL STATE OF TEXAS

Before me, the undersigned authority, on this day personally appeared \_TEXAS HILL COUNTRY COTTAGES, LLC who after being by me duly sworn, upon oath state that they are the owner of record of that certain tract or parcel of land lying and being situated in Comal County, Texas, and being more particularly described as follows:

2 UNIT/PHASE/SECTION	BLOCK <u>&amp; 270</u> L	OT CANYON LAKE ACRES	SUBDIVISION
IF NOT IN SUBDIVISION:	ACREAGE		SURVEY
boundary between the properti	ies. These properties car	facility for the referenced propertie nnot be sold separately and must be	
Any buyer or transferee is her	reby notified of this re-	quirement.	SEP 25 2018
WITNESS MY/OUR HAND	(S) on t VOID	September, 20 18.	COUNTY ENGINEER
JAY SETCHELL - MANAGER SWORN TO AND SUBSCRI	BED BEFORE ME or	this 17 day of Septemb	ec20 18.
Notary Public Signatur	l		
ALEX RUE  Notary Public State of Texas ID # 13067096-9 My Comm. Expires 05-20-2020		Filed and Recorded Official Public Re Bobbie Koepp Coun	cords tv Clerk

Comal County Texas 09/25/2018 11:27:41 AM TERRI 2 Page(s)
201806037677

Bobbie Koepp



### Ritzen, Brenda

From: Ritzen, Brenda

**Sent:** Tuesday, January 15, 2019 10:07 AM

**To:** 'Greg Johnson' **Subject:** RE: Permit 108167

#### Greg,

Please provide corresponding documentation regarding the acquisition of the right of way.

Thank you,

Brenda Ritzen, OS0007722 Environmental Health Coordinator Comal County Engineers Office 195 David Jonas Drive New Braunfels, Texas 78132 830-608-2090 www.cceo.org

From: Greg Johnson <gregjohnsonpe@yahoo.com>

**Sent:** Monday, January 14, 2019 10:08 AM **To:** Ritzen, Brenda <rabbjr@co.comal.tx.us>

Subject: Re: Permit 108167

Attached is the revised.

You should have already received the corrected affidavit.

Thanks, Greg

Send for Greg W. Johnson, P.E., R.S.)

170 Hollow Oak

New Braunfels, TX 78132

Office/Fax (830) 905-2778

Email: gregjohnsonpe@yahoo.com

On Wed	nesday	r, October 31, 2018, 2:09:26 PM CDT, Ritzen, Brenda < <u>rabbjr@co.comal.tx.us</u> > wrote:
Re:	Texas Hill Country Cottages, LLC	
	Canyo	on Lake Acres Unit 2 Lots 269 & 270 and remainder of Lots 268 & 267
	Applic	ation for Permit for Authorization to Construct an On-Site Sewage Facility
Greg,		
		I your submittal for the referenced permit and found the following information is still needed before I can ssing the referenced permit submittal:
	1.	Provide corresponding deed information for the remainder of Lot 267 as indicated.
	2.	Provide exemption deeds prior to 1/01/88 for the remainder of Lots 267 & 268.
	3.	Maintain required 20 ft. setback from the edge of the spray area to the property lines.
	4. ma	Revise the permit application, Certification of OSSF Requiring Maintenance, and planning materials to tch the revised legal description.
Thank y	ou,	
Brenda	Ritzen,	OS0007722
Environ	mental l	Health Coordinator
Comal C	County I	Engineers Office
195 Dav	id Jona	as Drive
New Bra	aunfels,	Texas 78132
830-608	-2090	
WWW.CC	eo.org	

From: Ritzen, Brenda
To: "Greg Johnson"
Subject: Permit 108167

Date: Wednesday, October 31, 2018 2:07:00 PM


Re: Texas Hill Country Cottages, LLC


Canyon Lake Acres Unit 2 Lots 269 & 270 and remainder of Lots 268 & 267 Application for Permit for Authorization to Construct an On-Site Sewage Facility

#### Greg,

I have reviewed your submittal for the referenced permit and found the following information is still needed before I can continue processing the referenced permit submittal:

- 1. Provide corresponding deed information for the remainder of Lot 267 as indicated.
- 2. Provide exemption deeds prior to 1/01/88 for the remainder of Lots 267 & 268.





Thank you,
Brenda Ritzen, OS0007722
Environmental Health Coordinator
Comal County Engineers Office
195 David Jonas Drive
New Braunfels, Texas 78132
830-608-2090
www.cceo.org

### \* \* \* COMAL COUNTY OFFICE OF ENVIRONMENTAL HEALTH \* \* \*

APPLICATION FOR PERMIT FOR AUTHORIZATION TO CONSTRUCT AN ON-SITE SEWAGE FACILITY AND LICENSE TO OPERATE

GREG W. JOHNSON, P.E.  Iddress 170 HOLLOW OAK  NEW BRAUNFELS, TX 78132  (830) 905-2778  gregjohnsonpe@yahoo.com  Method: Mail Email  Lot 267,7268,269,270 Block  CANYON LAKE Zip 78133
170 HOLLOW OAK
(830) 905-2778  gregjohnsonpe@yahoo.com  Method:
gregjohnsonpe@yahoo.com  Method: Mail Email  2 Lot 267,7268,269,270 Block
Method: ☐ Mail ☑ Email  2 Lot 267,7268,269,270 Block
2 Lot <u>267,<b>72</b>68,269,270</u> Block
CANYON LAKE Zip 78133
CANYON LAKE Zip 78133
HOUSE
SED 0 =
SEP 25 2018
COUNTY ENGINEER
nd needed for treatment units and disposal area)
er Of Occupants
corps of Engineers (USACE) flowage easement?
SSF improvements within the USACE flowage easement)
_
□ No
alea information and door not consoal any material feets
alse information and does not conceal any material facts.  upon the above described property for the purpose of  odplain Administrator has performed the reviews required  ed with this permit application, as applicable.
upon the above described property for the purpose of adplain Administrator has performed the reviews required

Revised July 2018

### \* \* \* COMAL COUNTY OFFICE OF ENVIRONMENTAL HEALTH \* \* \*

APPLICATION FOR PERMIT FOR AUTHORIZATION TO CONSTRUCT AN ON-SITE SEWAGE FACILITY AND LICENSE TO OPERATE

Planning Materials & Site Evaluation as Required Completed By GREG W. JOHNSON, P.E.
System Description PROPRIETARY; AEROBIC TREATMENT AND SURFACE IRRIGATION
Size of Septic System Required Based on Planning Materials & Soil Evaluation
Tank Size(s) (Gallons) SOLAR AIR SA600 LP Absorption/Application Area (Sq Ft) 2827
Gallons Per Day (As Per TCEQ Table III)180  (Sites generating more than 5000 gallons per day are required to obtain a permit through TCEQ)
Is the property located over the Edwards Recharge Zone? Yes No  (If yes, the planning materials must be completed by a Registered Sanitarian (R.S.) or Professional Engineer (P.E.))  SEF 2 5 2018
(if yes, the R. S. or P. E. shall certify that the OSSF design complies with all provisions of the existing WPAP.)  COUNTY ENGINEER
If there is no existing WPAP, does the proposed development activity require a TCEQ approved WPAP? Yes No
(If yes, the R.S. or P. E. shall certify that the OSSF design will comply with all provisions of the proposed WPAP. A Permit to Construct will not be issued for the proposed OSSF until the proposed WPAP has been approved by the appropriate regional office.)
Is the property located over the Edwards Contributing Zone?  No
Is there an existing TCEQ approval CZP for the property? Yes No
(if yes, the P.E. or R.S. shall certify that the OSSF design complies with all provisions of the existing CZP)
If there is no existing CZP, does the proposed development activity require a TCEQ approved CZP? Yes No (if yes, the P.E. or R.S. shall certify that the OSSF design will comply with all provisions of the proposed CZP. A Permit to construct will) not be issued for the proposed OSSF until the CZP has been approved by the appropriate regional office.)
Is this property within an incorporated city? Yes No
If yes, indicate the city:  GREG W. JOHNSON  OF 67587  OF GISTER  FIRM #2585
By signing this application, I certify that:  - The information provided above is true and correct to the best of my knowledge.  - I affirmatively consent to the online posting/public release of my e-mail address associated with this permit application, as applicable  September 10, 2018  Page 2 of 2

195 David Jonas Dr., New Braunfels, Texas 78132-3760 (830) 608-2090 Fax (830) 608-2078

### **AFFIDAVIT**





CERTIFICATION

VOID

ING MAINTENANCE

According to Texas Commission on (OSSF's), this document is filed in the

(Notary Seal Here)

ty Rules for On-Site Sewage Facilities Comal County, Texas.

T

The Texas Health and Safety Code, Chapter 366 authorizes the Texas Commission on Environmental Quality (TCEQ) to regulate on-site sewage facilities (OSSFs). Additionally, the Texas Water Code (TWC), § 5.012 and § 5.013, gives the commission primary responsibility for implementing the laws of the State of Texas relating to water and adopting rules necessary to carry out its powers and duties under the TWC. The commission, under the authority of the TWC and the Texas Health and Safety code, requires owner's to provide notice to the public that certain types of OSSFs are located on specific pieces of property. To achieve this notice, the commission requires a recorded affidavit. Additionally, the owner must provide proof of the recording to the OSSF permitting authority. This recorded affidavit is not a representation or warranty by the commission of the suitability of this OSSF, nor does it constitute any guarantee by the commission that the appropriate OSSF was installed.

 $_{
m II}$ 

An OSSF requiring a maintenance contract, according to 30 Texas Administrative Code §285.91(12) will be installed on the property described as (insert legal description):

LOT	CANYON LAKE ACRES	SUBDIVISION
		SURVEY
OID	TEXAS HILL COUNTRY COTT.	AGES, LLC,
n aerobic tr	eatment system for a single famil 30 days or maintain the system	fter y SEP <b>25</b> 2018
		COUNTY INGLESE e
F Depte	ember ,20_18	
		_
•		
	intenance on aerobic tract within operty, the pannice.  Owner (TO AND SU	DID  Intenance contract for the first two years. As a aerobic treatment system for a single family ract within 30 days or maintain the system operty, the permit for the OSSF shall be fight the planning materials for the OSSF can be







SEP 25 2018

### Routine Maintenance and Inspection Agreement

General

COUNTY ENGINEER This Work for Hire Agreement (hereinafter referred to as this "Agreement") is entered into by and between TEXAS HILL COUNTRY COTTAGES, LLC (referred to as "Client") and Aerobic Services of South Texas (Thomas W Hampton MP 349) (hereinafter referred to as "Contractor") located at 15188 FM 306, Texas 78133 (830) 964-2365. By this Agreement the Contractor agrees to render professional service, as described herein, and the Client agrees to fulfill the terms of this Agreement as described herein.

This contract will provide for all required inspections, testing and service for your Aerobic Treatment System. The policy will include the following:

- 1. 3 inspections a year/services calls (at least one every 4 months), for a total of 6 over the two year period including inspection, adjustment and servicing of the mechanical, electrical and other applicable component parts to ensure proper function. This includes inspecting control panel, air pumps, air filters, diffuser operation, Any alarm situation affecting the proper function of the Aerobic process will be address within a 48-hour time Frame. Repair work on non-warranty parts will include price for parts & labor. The prices will be quoted before work is performed.
- check for color, turbidity, scum overflow and 2. An effluent quality inspection cons examination for odors. A test for chloring be taken and reported as necessary.
- 3. If any improper operation is observed, which cannot be corrected at the time of the service visit, you will be notified immediately in writing of the conditions and estimated date of correction.
- The customer is responsible for the chlorine tablets; they must be filled before or during the service visit.
- 5. Any additional visits, inspections or sample collection required by specific Municipalities, Water/River Authorities, and County Agencies the TCEQ or any other authorized regulatory agency in your jurisdiction will be covered by this policy.

The Homeowners Manual must be strictly followed or warranties are subject to invalidation. Pumping of studge build-up is not covered by this policy and will result in additional charges.

#### ACCESS BY CONTRACTOR

The Contractor or anyone authorized by the Contractor may enter the property at reasonable times without prior notice for the purpose of the above described Services. The contractor may access the System components including the tanks by means of excavation for the purpose of evaluations if necessary. Soil is to be replaced with the excavated material as best as possible.

**Termination of Agreement** 

Either party may terminate this agree per contemporary without fault of the terminating party. If this Agreement is so terminated, the Contractor will immediately notify the appropriate health authority of the termination.

Limit of Liability

In no event shall the Contractor be liable for indirect, consequential, incidental or punitive damages, whether in contract tort or any other theory. In no event shall the Contractor's liability for direct damages exceed the price for the services described in this Agreement.

Dispute Resolution

If a dispute between the Client and the Designer arises that cannot be settled in good faith negotiations then the parties shall choose a mutually acceptable arbitrator and shall share the cost of the arbitration services equally.

Entire Agreement

Model #

This Agreement contains the entire agreement of the parties, and there are no other promises or conditions in 2018 any other agreement either oral or written.

COUNTY ENGINEER

Severability

If any provision of this Agreement shall be held to be invalid or unenforceable for any reason, the remaining provisions shall continue to be valid and enforceable. If a court finds that any provision of this agreement is invalid or unenforceable, but that by limiting such provision it would become valid and enforceable, then such provision shall be deemed to be written, const

Legal Description: 331 PERSIMMON PASS

Property Address: RANCHO DEL LAGO, PHASE 9, LOT 40 HOME OWNER SERVICE PROVIDER TEXAS HILL COUNTRY COTTAGES, LLC Aerobic Services of South Texas Inc. Name Name 824 SHELLY DRIVE 15188 FM 306 Address CANYON LAKE TX 7813 Canyon Lake, Texas 78133 City, State City. State (830) 964 -713-824-265 OS0024597/MP349 Phone Thomas Hampton Signature of Home Owner Signature of Service Provider and License # EFFECTIVE DATE EXPIRED DATE INSTALLED

The effective date of this initial maintenance contract shall be the date license to operate is issued.

Blower/Panel Serial #

### **ON-SITE SEWERAGE FACILITY** SOIL EVALUATION REPORT INFORMATION

Date Soil Survey Performed: September 07, 2018	
Site Location: CANYON LAKE ACRES, NIT 2, LOTS 20, 268, 269 & 270	
Proposed Excavation Depth: N/A	
Requirements:  At least two soil excavations must be performed on the site, at opposite ends of the proposed disposal area.	RECEIVED
Locations of soil boring or dug pits must be shown on the site drawing.  For subsurface disposal, soil evaluations must be performed to a depth of at least two feet below the proposed excavation depth. For surface disposal, the surface horizon must be evaluated.	SEP 25 2018
proposed excavation depth. For surface disposal, the surface horizon must be evaluated.  Describe each soil horizon and identify any restrictive features on the form. Indicate depths where features	UNTY ENGINEER

Depth (Feet)	Texture Class	Soil Texture	Gravel Analysis	Drainage (Mottles/ Water Table)	Restrictive Horizon	Observations
10"	Ш	CLAY LOAM	N/A	NONE OBSERVED	LIMESTONE @ 10"	BROWN
			VOID			


Depth (Feet)	Texture Class	Soil Texture	Gravel Analysis	Drainage (Mottles/ Water Table)	Restrictive Horizon	Observations
2	SAME		AS		ABOVE	
4						

I certify that the findings of this report are based on my field	observations and are accurate to
the best of my ability.	
171	09/07/18
Greg W. Johnson, P.E. 67587-F2585, S.E. 11561	Date l

### OSSF SOIL EVALUATION REPORT INFORMATION

Date: September 10, 2018	
Applicant Information:	
	Evaluator Information:
Name: TEXAS HILL COUNTRY COTTAG  Address: 824 SHELLY DRIVE	me: Greg W. Johnson, P.E., R.S., S.E. 11561
	dress: 170 Hollow Oak
	y: New Braunfels State: Texas  Code: 78132 Phone & Fax (830)905-2778
Zip Code Filolie (13) 624 2656	p Code. 18132   Phone & Pax 1830/303-2118
Property Location:	Installer Information:
Lot MEZOW Unit 2 Blk Subd. CANYON LAKE ACRES	Name:
Street Address: 1012 ROADRUNNER LANE	Company:
City: CANYON LAKE Zip Code: 78133	Address:
Additional Info.: LOTS 267, 268, 269 & 270	City:State:
	Zip Code:Phone
Topography: Slope within proposed disposal area:6	<u></u> %
Presence of 100 yr. Flood Zone:	YESNO_X
Existing or proposed water well in nearby area.	YESNO_X RECEIVED
Presence of adjacent ponds, streams, water impoundments	YES NO X
Presence of upper water shed	YES NO X SEP 2 5 2018
Organized sewage service available to lot	YESNO_X
	COUNTY ENGINEER
Design Calculations for Aerobic Treatment with Spray	irrigation:
Commercial	
Q =GPD	37 N
Residential Water conserving fixtures to be utilized? Yes	Total so, ft. living area 1200
Number of Bedrooms the septic system is sized for: 2	
Q gal/day = (Bedrooms +1) * 75 GPD - (20% reduction for	water conserving fixtures)
Q = (2 + 1)*75-(20%) = 180	
Trash Tank Size 376 Gal. TCEO Approved Aerobic Plant Size 600 G.P.	D
TODA TIPPIO (CE TICIOCIE I ILIII CILE	2813 sq. ft.
Req'd Application Area = Q/Ri = 180 Application Area Utilized = 2827	2013 Sq. 1t.
Physical Propries and 12 Com (2) 41 Poi (Pedies	hat A 5 HP 18 G P M series or equivalent)
Pump Requirement 12 Gpm @ 41 Psi (Redjac Dosing Cycle: ON DEMAND or X TIM	ED TO DOSE IN PREDAWN HOURS
Pump Tank Size = 778 Gal. 18.75 Gal/in	ich
Reserve Requirement = 60 Gal. 1/3 day flow.	
Alarms: Audible & Visual High Water Alarm & Visual Air	Pump malfunction
With Chlorinator NSF/TCEQ APPROVED	T samp manager
SCH-40 or SDR-26 3" or 4" sewer line to tank	
Two way cleanout	
Pop-up rotary sprinkler heads w/ purple non-potable lids	
1" Sch-40 PVC discharge manifold	
APPLICATION AREA SHOULD BE SEEDED AND MAII	NTAINED WITH VEGETATION.
I HAVE PERFORMED A THOROUGH INVESTIGATION BE	TING A DEGISTEDED DROFESSIONAL ENGINEER
AND SITE EVALUATOR IN ACCORDANCE WITH CHAPT	
(REGARDING RECHARGE FEATURES), TEXAS COM	
(EFFECTIVE DECEMBER 29, 2016)	OF A
^ /· ·	TATE
/WX	118 18
7 . 0 0	GREG W. JOHNSON
GREG W. JOHNSON, P.E. F#002585 - S.E. 11561	67587 0 2
	ON TEGISTERE THE
	FIRM #2585
	Maritality

NOTE:
NO OSSF SYSTEM CAN BE INSTALLED ON
THE SAME PROPERTY AS THE SINGLE
FAMILY DWELLING, DUE TO PLACEMENT OF
HOUSE AND SIZE OF LOT. TEXAS HILL
COUNTRY COTTAGES, LLC. OWNS ALL
FOUR PROPERTIES.







TEXAS HILL COUNTRY CO	EJS II						
STREET ADDRESS: 1012 ROAD RUNNER LA	NE						
LEGAL DESC: CANYON LAKE ACRES	UNIT/SECTION/PHASE:	2	BLOCK: 0	LOT:	267, 2	68, 264	& 270
PREPARED BY: GREG W. JOHNSON, P.E.	F#002585 SCALE:	1"=4	0' DATE: 9/	10/20	18	REVISED:	

From: Ritzen, Brenda
To: "Greg Johnson"
Subject: Permit 108167

Date: Wednesday, October 03, 2018 11:19:00 AM

RE: Texas Hill Country Cottages, LLC

Canyon Lake Acres Unit 2 Lots 267, 268, 269, & 270

Application for Permit for Authorization to Construct an On-Site Sewage Facility

### Greg,

The following information is needed before I can continue processing the referenced permit submittal:

- 1. Revise the legal description of the property to reflect the 0.382 acres/part of Lot 268, as indicated within the recorded deed.
- 2. The permit application, Affidavit to the Public and all planning materials must be corrected to reflect the correct property description for the 0.382 acre/part of Lot 268.
- 3. Provide exemption deed prior to 1/01/88 for the 0.382 acre part of Lot 268.
- 4. Maintain the required 20 ft. setback from the property lines with the edge of the spray area.
- 5. Revise as needed and resubmit.

#### Thank you,

Brenda Ritzen, OS0007722 Environmental Health Coordinator Comal County Engineers Office 195 David Jonas Drive New Braunfels, Texas 78132 830-608-2090 www.cceo.org

### Capital Title GF# <u>18 - 35 400 3 - 8</u>V

#### **General Warranty Deed**

Notice of confidentiality rights: If you are a natural person, you may remove or strike any or all of the following information from any instrument that transfers an interest in real property before it is filed for record in the public records: your Social Security number or your driver's license number.

Date: May 4, 2018

Grantor: Larry Wesch, a single person

Grantor's Mailing Address: P.O. Box 185, Fischer, TX 78623

Grantce: Texas Hill Country Cottages, LLC, a Texas limited liability company

Grantee's Mailing Address: 824 Shelty Drive, Canyon Lake, TX 78133

Consideration: the sum of TEN DOLLARS (\$10.00) cash, and other good and valuable

consideration

Property (including any improvements):

Tract 1:

Lot 267, Canyon Lake Acres, Unit No. 2, an Addition in Comal County, Texas, according to the Map or Plat recorded in Volume 1, Page 50, Map and Plat Records of Comal County, Texas; and Save and Except all of that portion conveyed tin Dccd executed by B. R. Mericle to the State of Texas dated November 30, 1972, filed December 18, 1972, recorded in Volume 201, Page 899, Real Property Records, Comal County, Texas.

Tract 2:

Being a 0.382 acre tract of land, more or less, being a part of Lot 268, and all of Lots 269 and 270, Canyon Lake Acres, Unit No. 2, an Addition in Comal County, Texas, according to the Map or Plat recorded in Volume 1, Page 50, Map and Plat Records of Comal County, Texas, and all bearings referred to in this description are referenced to a bearing of N 51° 47' 00" W between monumentation found along the Northeast line of F.M. Highway No. 306, said 0.382 acre tract of land surveyed under the supervision of Richard A. Goodwin, RPLS No. 4069, S. Craig Hollming, Inc., and being more particularly described as follows:

BEGINNING: At a 1/2" iron pin found on the East line of Road Runner Lanc, for the Northwest corner of the above referenced Lot 270, same being the Southwest corner of Lot 271, Canyon Lake Acres, Unit No. 2, for the Northwest corner of this tract;

THENCE: With the North line of the above referenced Lot 270, the South line of said Lot 271, N 87° 00′ 44″ E 190.05 feet to a 1/2″ iron pin found on the West line of Lot 134 of The Point Rancho De Lago, Phase 3, recorded in Volume 8, Pages 291-292 of the Map and Plat Records of Comal County, Texas, for the Northeast corner of the above referenced Lot 270, the Southeast corner of Lot 271, for the Northeast corner of this tract;

THENCE: With the West linc of said Lot 134, the East line of the above referenced Lots 270,269 and 268, S 02° 48' 58" E 89.72 feet to a ½" iron pin found in same, for the Southeast corner of the above referenced Lot 268, for the Southeast corner of this tract;

THENCE: With the South line of the above referenced Lot 268, S 87° 03' 23" W 150.76 feet to a ½" iron pin found on the present Northeast line of F.M. Highway No. 306, for the Southwest corner of this tract;

THENCE: With the Northeast line of F.M. Highway No. 306, N 51° 47' 00" W 45.60 feet to a concrete monument found in same, for the original Northwest corner of the above referenced Lot 268, the Southwest corner of the above referenced Lot 269, for a corner of this tract;

THENCE: Continuing with the Northeast line of F.M. Highway No. 306, N 31° 38' 34" W 33.62







feet to a 1/2" iron pin found for the Northwest corner of the above referenced Lot 269, same being the Southwest corner of the above referenced Lot 270, for a corner of this tract;

THENCE: With the East line of Road Runner Lane, N 17° 45' 36" E 32.13 feet to the Point of Beginning and containing 0.382 acres of land, more or less.

Reservations from Conveyance: None

Exceptions to Conveyance and Warranty:

This conveyance, however, is made and accepted subject to any and all restrictions, encumbrances, easements, covenants and conditions, if any, relating to the hereinabove described property as the same are filed for record in the County Clerk's Office of Comal County, Texas.

Grantor, for the Consideration and subject to the Reservations from Conveyance and the Exceptions to Conveyance and Warranty, grants, sells, and conveys to Grantee the Property, together with all and singular the rights and appurtenances thereto in any way belonging, to have and to hold it to Grantee and Grantee's heirs, successors, and assigns forever. Grantor birds Grantor and Grantor's heirs and successors to warrant and forever defend all and singular the Property to Grantee and Grantee's heirs, successors, and assigns against every person whomsoever lawfully claiming or to claim the same or any part thereof, except as to the Reservations from Conveyance and the Exceptions to Conveyance and Warranty.

When the context requires, singular nouns and pronouns include the plural.

EXECUTED this

day of May, 2018.

Larry Wesch

THE STATE OF

2018 by Larry Wesch.

COUNTY OF COMME

smel \$

The foregoing instrument was acknowledged before me on the

DEANNA N. TALLEY

Notary Public, State of Texas

Comm. Expires 10-12-2019 Notary ID 10232358

AFTER RECORDING, RETURN TO:

24 Shelly Dr 2 anyon Lave 1+ 78133 NOTALE OF

PREPARED IN THE LAW OFFICE OF Shaddock & Associates, P. C. 2400 N. Dallas Parkway, Stc. 560 Plano, Texas 75093

Filed and Recorded
Official Public Records
Bobbie Koepp, County Clerk
Comal County, Texas
05/04/2018 04:20:29 PM
NANCY 2 Pages(s)
201806017388



# CCEO COPY

			****
Texas High	way Departme	ent	VOL 201 PAGE 745
Form D-15			ANC. FOT BYCE 140
Page 1 of			· · ·
Rev. 10-6			400040
		•	120648
			DEED
		* . * *	to fill the second of the seco
		******	
THE STATE	OF TEXAS		
COUNTY OF	Coma1		KNOW ALL MEN BY THESE PRESENTS:
That	_I.Mrs.D	orothy M. Cr	аглеу
			:
urguman Co	mmission, re	ceipt of which	e of Texas, acting by and through the State is hereby acknowledged, and for which no lie
is retained of Grant, or parcel larly desc	d, either exp Bargain, Sell of land in	ceipt of which pressed or imp l and Convey u Comal lows, to wit:	e of Texas, acting by and through the State is hereby acknowledged, and for which no lie lied, have this day sold, and by these presen nto the State of Texas, all that certain trac County, Texas, and being more particu
is retained Grant, or parcel larly described Being a Canyon L day of Juneal Records	ed, either explanation, Selfor I and in	ceipt of which pressed or imp 1 and Convey u Comal lows, to wit: t 268, Canyo , Inc. to Bu and recorde	e of Texas, acting by and through the State is hereby acknowledged, and for which no lie lied, have this day sold, and by these presen nto the State of Texas, all that certain trac
is retained of Grant, or parcel larly described Canyon L day of Jued Rec described Beginnin existing Relocati	part of Los ake Shores, une, 1969, ords of Cox dby metes g at the part on, said con,	ceipt of which pressed or imp 1 and Convey u Comal lows, to wit: t 268, Canyo , Inc. to Bu and recorde mal County, and bounds resent North line of a corner being	e of Texas, acting by and through the State is hereby acknowledged, and for which no lie lied, have this day sold, and by these presen nto the State of Texas, all that certain trac County, Texas, and being more particu an Lake Acres, Unit 2, as conveyed by tree D. Carney by deed dated the 26th d in Volume 171, Pages 329-330 of the Texas, and being more particularly
is retained of Grant, or parcel larly descriped a Canyon L day of Jueed Recodescribe Beginning existing Relocati	part of Lorance of Lorance Shores, 1969, ords of Cond by metes  g at the part of Lorance of Lorance of Cond by metes  g at the part of Lorance of Cond of Cond of Cond of Cond of Cond of Cond by metes  g at the part of Lorance of Lorance of Cond o	ceipt of which pressed or imp 1 and Convey un Comal lows, to wit:  t 268, Canyon, Inc. to But and recorder mal County, and bounds  resent North line of a corner being the center to the	e of Texas, acting by and through the State is hereby acknowledged, and for which no lie lied, have this day sold, and by these presen nto the State of Texas, all that certain trac County, Texas, and being more particular to Lake Acres, Unit 2, as conveyed by arrel D. Carney by deed dated the 26th id in Volume 171, Pages 329-330 of the Texas, and being more particularly as follows, to-wit:  neest corner of Lot 268, lying in the county road known as the Hancock Road 62.2 feet at right angles from Engine
is retained of Grant, or parcel larly described a Canyon L day of Jueed Recodescribed Beginnin existing Relocati Station Thence Sa distanthe South	part of Lorales of Shores une, 1969, ords of Cond by metes on, said confidence of 45.6 the second by	ceipt of which pressed or imp I and Convey un Comal Iows, to wit:  t 268, Canyo, Inc. to Bu and recorder mai County, and bounds  resent North line of a corner being the center  E., along the feet to a purchased and the center with said with said with said converted and the center with	e of Texas, acting by and through the State is hereby acknowledged, and for which no lie lied, have this day sold, and by these presente the State of Texas, all that certain trac County, Texas, and being more particular to the State of Texas, and being more particular to the State of Texas, and being more particular to the State of Texas, and being more particular to the Texas, and being more particular to as follows, to-wit:  Inwest corner of Lot 268, lying in the county road known as the Hancock Road 62.2 feet at right angles from Engine line of proposed F.M. Highway No. 306 the proposed Northeast right-of-way line of the South line a distance of 18.1 feet to the South line a distance of 18.1 feet to the South line existing Northeast line

# CCEO COPY

VOL 201 PAGE 746

Form D-15-14 Page 2 of 4 Rev. 10-61

A Charles

A copy of the right-of-way map of the above mentioned highway is on file in the right-of-way records of the Texas Highway Department District Office at San Antonio, Texas, to which map reference is made for further description.

SAVE and EXCEPT, HOWEVER, it is expressly understood and agreed that Grantors are retaining title to the following improvements located on the above described property, to wit:

None

Grantors covenant and agree to remove the above described improvements from said land by \_\_\_\_\_\_, 19\_\_\_\_, subject, however, to such extensions of time as may be granted by the Ctate in writing; and if, for any reason, Grantors fail or refuse to remove same within said period of time prescribed, then, without any further consideration, the title to all or any part of such improvements not so removed shall pass to and vest in the State of Texas forever.

Grantors reserve all of the oil, gas and sulphur in and under the land herein conveyed but waive all rights of ingress and egress to the surface thereof for the purpose of exploring, developing, mining or drilling for same; however, nothing in this reservation shall affect the title and rights of the State to take and use all other minerals and materials thereon, therein and thereunder.

**12**08.43

# PT 2607

# CCEO COPY

lanu	och
longue	WEJCH
and to	•

romal County

Texas Highway Department Form D-15-14 Page 1 of 4 VOL 201 PAGE 899

120759

DEED

B. R. Merice 1969.

THE STATE OF TEXAS

Rev. 10-61

KNOW ALL MEN BY THESE PRESENTS:

Frankt Jae Sterns

That I. B. R. Mericle

All that certain tract or percel of land, situated in the County of Comal, State of Texas, and being a part of Lot 267, of the Canyon Lake Acres, Unit 2, as conveyed by Canyon Lake Shores, Inc. to Emmitt Joel Stevens, et ux by deed dated the 24th day of September, 1964 and recorded in Volume 141, Pages Al-A2 of the Deed Records of Comal County, Texas, same being a strip of land taken off the West and of Lot 267, Canyon Lake Acres, Unit 2, lying along and adjacent to the existing Northeast line of a county road known as the Hancock Read Relocation and being more particularly described by mates and bounds as follows, to-wit:

Beginning at the present Southwest corner of Lot 267, lying in the existing Northeast line of a county road known as the Hancock Road Relocation, said corner being N. 87° 06' E. 64.7 feet from Engineer's Station 91+99.3 on the center line of proposed F.M. Highway No. 306;

Thence N. 87° 06' E., with the South line of said Lot 267, a distance of 36.1 feet to a point in the processed Northeast right-of-way line of said highway;

Thence N. 51° 47° W., along the proposed Northeast right-of-way line, a distance of 43.6 feet to a point in the North line of said Lot 267;

Thence S. 87° 06° W., with said North line, a distance of 18.1 feet to the Northwest corner of Lot 267 lying in the existing Northeast line of the Hancock Road Relocation;

Thence in a Southeasterly direction with the Northeast line of said Hancock Road Relocation, same being a Southwest line of said Lot 267, a distance of 34.1 feet to the place of beginning and containing an area of 0.019 acres of land, more or less, all out of the John H. Cocke Survey No. 34, Abstract No. 104.

# CCEO COPY

VOL 201 PAGE 900

Form D-15-14 Page 2 of 4 Rev. 10-61

A copy of the right-of-way map of the above mentioned highway is on file in the right-of-way records of the Texas Highway Department District Office at San Antonio, Texas, and on file in the right-of-way records of the Texas Highway Department in Austin, Texas, to which map reference is made for further description.

SAVE and EXCEPT, HOWEVER, it is expressly understood and agreed that Grantors are retaining title to the following improvements located on the above described property, to wit:

NONE

Grantors covenant and agree to remove the above described improvements from said land by \_\_\_\_\_\_\_, 19\_\_\_\_\_\_, subject, however, to such extensions of time as may be granted by the State in writing; and if, for any reason, Grantors fail or refuse to remove same within said period of time prescribed, then, without any further consideration, the title to all or any part of such improvements not so removed shall pass to and vest in the State of Texas forever.

Grantors reserve all of the oil, gas and sulphur in and under the land herein conveyed but waive all rights of ingress and egress to the surface thereof for the purpose of exploring, developing, mining or drilling for same; however, nothing in this reservation shall affect the title and rights of the State to take and use all other minerals and materials thereon, therein and thereunder.

Inspection Date: June 6<sup>th</sup>
Service expires: 2/21/2021
Subdivision: Canyon Lake Acres

Billing Address:

1012 Roadrunner, Canyon Lake, Tx 78133

Carrie West Contact: Texas Hill Country Cottagos 1659 State Highway 46 W. Ste. 115-200 New Braunfels, TX 78132

830.624.5859

## **Clear Choice Septic Services**

### Routine Maintenance Inspection Report

This Inspection Report Record shall be completed, signed and dated after each inspection

Site Address:

Lot: 267-270

1012 Roadrunner, Canyon Lake, 78133

Permit: 108167

Number: 713-824-2650 スパロース6イー/6/7(Hr) Manufacture/Size: Solar Aire-600 GPD				
YES	NO	TESTS F	REQUIRED AND RE	SULTS:
305,	and the state of t		Required Yes/ No	Results mg/ 1 mpn 100mi or
1/	PACACA PA			Trace
		TSS	Y /N	
NIA				Clear
		C1	(Ý)/N	1.0
/				
		d increase and a second		
/				
NA				
(YES	NO			
o the following:	County:	Comal / Pro		
	YES  3 ps,  //  //  //  //  //  //  o the following:	YES NO  YES NO  YES NO  Oncress No. (Neclee 6)  O the following: County:	YES NO TESTS F  3 ps,  TSS  C1  YES NO  TSS  C1  YES NO  TOTAL  C1  YES NO  TOTAL  C1  YES NO  Departure Time: (2./0)	Type of System: Spray  YES NO TESTS REQUIRED AND RE  Required Yes/ No  TSS Y/N  TSS Y/N  C1 (A)/ N  YES NO  Other following: County: Comal / Property Owner.

Inspection Date: OCT 9<sup>45</sup> Service expires: 2/21/2021 Subdivision: Canyon Lake Acres

1659 State Highway 46 W. Ste. 115-200 New Braunfels, TX 78132

830.624.5859

## Clear Choice Septic Services

### **Routine Maintenance Inspection Report**

This Inspection Report Record shall be complete	d, signed and dated after each inspection
---	---

Billing Address:

1012 Roadrunner, Canyon Lake, Tx 78133

Site Address:

1012 Roadrunner, Canyon Lake, 78133

spoke

Contact: Carrie West

Number: 210-264-1617

Lot: 267-270 County: Comal Permit: 108167

Manufacture/Size: Solar Aire-600 GPD

Type of System: Spray

INSPECTION ITEM:	YES	NO	TESTS R	EQUIRED AND RE	SULTS:
Compressor Pressure Reading/ Aerators ACFM:	3051			Required Yes/ No	mg/ 1 mpi
Filters are intact and operating:			NAMES AND THE		100mi or Trace
Irrigation Pumps have correct pressure:	1		TSS	YN	
Recirculation Pumps active on system:	NA				Clear
Disinfection Device present & functioning properly:			C1	(A) N	1.0
Chlorine Supply visible:					
Electrical Circuits functional:					
Sprinklers/ Drip Pad operating correctly:					
Dripfield/ Sprayfield Vegetation present:	/				•
Back Flush Dripfield, if applicable:	NA				
Access Ports are Secured:	YES	NO			
Service or repairs completed to system: Cleaned Air filter on Con spribblis. Set Limi	repressor o	heched	morthey	floats +	
Copies of this Report have been sent to				perty Owner.	
Date completed: 0-9-19 Arrival Time	e: 1:25 D	eparture Time	e: <u>/: 55</u>		

Inspection Date: feb 13th 9:30-10:00 Service expires: 2/21/2021

Subdivision: Canyon Lake Acres

1659 State Highway 46 W. Ste. 115-200 New Braunfels, TX 78132 830.624.5859

## Clear Choice Septic Services

### Routine Maintenance Inspection Report

This Inspection Report	Record shall be completed,	signed an	d dated after	each inspection
Dillian Address.				

Billing Address:

Site Address:

1012 Roadrunner, Canyon Lake, Tx 78133

1012 Roadrunner, Canyon Lake, 78133

spoke feb 10th @

Contact: Carrie West

Lot: 267-270

Permit: 108167

Number: 210-264-1617

County: Comal

Manufacture/Size: Solar Aire-600 GPD

Type of System: Spray

**Customer Notes:** 

INSPECTION ITEM:	YES	NO	TESTS R	EQUIRED AND RE	SULTS:
Compressor Pressure Reading/ Aerators ACFM:	3051			Required Yes/ No	Results mg/ 1 mpn
Filters are intact and operating:	1,				100mi or Trace
Irrigation Pumps have correct pressure:	/		TSS	YN	
Recirculation Pumps active on system:	NIA				Clear
Disinfection Device present & functioning property:	/		C1	<b>⊘</b> N	Clear 1.0.
Chlorine Supply visible:	1		•		
Electrical Circuits functional:	/				
Sprinklers/ Drip Pad operating correctly:					
Dripfield/ Sprayfield Vegetation present:	/				
Back Flush Dripfield, if applicable:	NA				
Access Ports are Secured:	YES	NO	7		

Service or repairs completed to system: cleaned sit fitter on compressor, chreched Sect tiller + rused System.	Chorine	Flooris	4 Sprincles
Set tilver + ruset System.			
Copies of this Report have been sent to the following: County: Co	omal / Propert	y Owner.	

Date completed: 2-/3-2026 Arrival Time: 9:16 Departure Time: 9:36

Maintenance Technician.

Maintenance Provider:

Inspection Date: ) Lane 16<sup>th</sup> /0:30 = 11:30 Service expires: 2/21/2021

Subdivision: Canyon Lake Acres

1659 State Highway 46 W. Ste. 115-200 New Braunfels, TX 78132

830.624.5859

## **Clear Choice Septic Services**

### **Routine Maintenance Inspection Report**

This Inspection Report Record shall be completed, signed and dated after each inspection

Billing Address:

1012 Roadrunner, Canyon Lake, Tx 78133

Site Address:

1012 Roadrunner, Canyon Lake, 78133

Spoke Contact: Carrie West

Number: 210-264-1617

Manufacture/Size: Solar Aire-600 GPD

Lot: 267-270

Permit: 108167

County: Comal

Type of System: Spray

Customer Notes:					
INSPECTION ITEM:	YES	NO	TESTS REQUIR	ED AND RE	SULTS:
Compressor Pressure Reading/ Aerators ACFM:	3051			Required Yes/ No	Results mg/ 1 mpn/ 100mi or
Filters are intact and operating:	/				Trace
Irrigation Pumps have correct pressure:			TSS	Y (N)	
Recirculation Pumps active on system:	NA		(Grab test method)		Clear
Disinfection Device present & functioning properly:			C1 (OTO test method)	(Ŷ N	1.0
Chlorine Supply visible:					
Electrical Circuits functional:					
Sprinklers/ Drip Pad operating correctly:					
Dripfield/ Sprayfield Vegetation present:					
Back Flush Dripfield, if applicable:	MA				
Access Ports are Secured:	(YES)	NO			
Service or repairs completed to system:  Cleaned Air filter ON  Sprukkless- Set file	Compresso	r, Check	red chilorihe,	floats	4

Copies of this Report have	been sent to the following: County:	Comal	/ Property Owner.
	4.5	4	
Date completed:6-/6-2020	Arrival Time: 10:42 Departure Tir	ne:////	
Maintenance Technician;	Just-		
Maintenance Provider:	Sur J		
	-		

Inspection Date: 07.7

Service expires: 2/21/2021 Subdivision: Canyon Lake Acres

**Customer Notes:** 

1659 State Highway 46 W. Ste. 115-200

New Braunfels, TX 78132

830.624.5859

### Clear Choice Septic Survices

### Routine Maintenance Inspection Report

This Inspection Report Record shall be completed, signed and dated after each inspection

**Billing Address:** 

Site Address:

1012

10-13-2026 1012 Roadrunner, Canyon Lake, Tx 78133

Roadrunner, Canyon Lake, 78133

**Contact: Carrie West** 

Lot: 267-270

Permit: 108167

Number: 210-264-1617

County: Comal

Type of System: Spray

Manufacture/Size: Solar Aire-600 GPD

INSPECTION ITEM:	YES	NO	TESTS REQUIRED A	AND RE	SULTS:
Compressor Pressure Reading/ Aerators ACFM:	3,65,1		i	equired es/ No	Results mg/ 1 mpn/
Filters are intact and operating:					100mi or Trace

Irrigation Pumps have correct pressure: **TSS** Recirculation Pumps active on system: (Grab test method) Disinfection Device present (OTO test method) & functioning properly:

Chlorine Supply visible: Electrical Circuits functional: Sprinklers/ Drip Pad operating correctly: Dripfield/ Sprayfield Vegetation present: Back Flush Dripfield, if applicable:

3 50/65		
Access Ports are Secured:	YES	NO

Service or repa	irs completed	I to system:		/	1	-		,
Wesneh	Lir fitte	ON COM	PRECOC.	diedued	disonie,	410 nts	pc -	Spriller
		1 Cused						
						,		

Copies of this Report have been sent to the following: County; Comal / Property Owner.

Date completed 12 202 Arrival Time: Departure Time: 10.20 Maintenance Technician:

Maintenance Provider:

Rext monday 9 30 1030

Inspection Date:

**Customer Notes:** 

Service expires: 2/21/2021 Subdivision: Canyon Lake Acres 1659 State Highway 46 W. Ste. 115-200 New Braunfels, TX 78132

830.624.5859

## Clear Choice Septic Services

### Routine Maintenance Inspection Report

This Inspection Report Record shall be completed, signed and dated after each inspection

Billing Address:

Site Address:

1012 Roadrunner, Canyon Lake, Tx 78133

1012 Roadrunner, Canyon Lake, 78133

Lot: 267-270

Permit: 108167

Contact: Carrie West

County: Comal

Type of System: Spray

Number: 210-264-1617

Manufacture/Size: Solar Aire-600 GPD

INSPECTION ITEM:	YES	NO	TESTS REQUIR	ED AND RE	SULTS:
Compressor Pressure Reading/ Aerators ACFM:	313			Required Yes/ No	Results mg/ 1 mpn/
Filters are intact and operating:	/				100mi or Trace
Irrigation Pumps have correct pressure:	/		TSS	Y/N)	. ,
Recirculation Pumps active on system:	1.75		(Grab test method)	, , , ,	cherry
Disinfection Device present & functioning properly:	MA		C1 (OTO test method)	Y/N	1.0
Chlorine Supply visible:	1				
Electrical Circuits functional:					
Sprinklers/ Drip Pad operating correctly:					
Dripfield/ Sprayfield Vegetation present:	/				
	7				
Back Flush Dripfield, if applicable:	11m				
Back Flush Dripfield, if applicable:  Access Ports are Secured:	YES	NO			
	YES	5+00 Fle		u, / ·'nċ·, vner.	



Canyon Lake: (830) 964-2365

Bastrop: (512) 303-6922
info@aerobicservices.com
bastrop@aerobicservices.com

MP349 / OS24597

					www.aerobicservices.com
To:	Carrie West		Tech:	Chris Ba	usch
1	1012 Road Runner L	n	Phone: (	(210) 264-1617	Date: 2024-04-20
(	Canyon Lake, TX 78	133	Alt Ph:	,	Service
Agency:	Comal				Due:
	Comal				
Permit No:	108167				
Inspection Type	Scheduled				_
<u>ltem</u>		<b>Operational</b>	<u>Inoperative</u>	Not Presen	<u>t</u>
Aerator:		[X]	[]	[]	Air Pressure: 82
Irrigation Pump	<b>)</b> :	[X]	[]	[]	
Air Compresso	r:	[X]	[]	[]	
Pump Screen:		[X]	[]	[]	
Chlorinator:		[X]	[]	[]	
Spray Field Veg	getation:	[X]	[]	[]	
Filters:		[X]	[]	[]	
Sprinkler / Drip	Backwash:	[X]	[]	[]	
Controls / Elect	tric Circuits:	[X]	[]	[]	
Test Results an	nd Observations: (A	s Required)			
	- (-			Mixed Liquor	all measurements in inches
Chlorine Residual (ppm):	0.01			Aeration:	0
Test Method:	Dpd			Sludge Lev	<u>vels</u>
BOD:				Clarifier:	0
TSS:			_	Pump:	12
Tank Lids Secure	d: Yes [X] / NO []				-
Pump Out Needed	d: Yes [X] / NO []				
Repairs Made	Yes [X] / NO [ ]				
Repairs and Comr System needs pu	ments: ımped, pump tank on	ly. Replaced 3' of	air line. Reconnecte	d bleach supply	line.
	3				
Inspector:				Date:	2024-04-20

Tom Hampton, VP MP349/OS24597

#### ROUTINE MAINTENANCE AND INSPECTION AGREEMENT



Carrie West 1012 Road Runner Ln Canyon Lake, TX 78133

P: (210) 264-1617

**COUNTY: Comal** 

PERMIT: 108167 AGREEMENT LENGTH: 12 mos.

DESCRIPTION	TERM	AMOUNT	TAX	TOTAL
Residential Service Contract	04/22/24 - '25	370.00		370.00

#### **GENERAL**

This Work for Hire Agreement (hereinafter referred to as this "Agreement") is entered into by and between the client named above (referred to as to "Client") and Aerobic Services (Thomas W. Hampton MP349) (hereinafter referred to as "Contractor") located at 15188 FM 306 Canyon Lake, Texas 78133. By this Agreement the Contractor agrees to render professional service, as described herein, and the Client agrees to fulfill the terms of this Agreement as described herein. This contract will provide for all required inspections, testing and service for your Aerobic Treatment System. The policy will include the following:

- 1. 3 inspections per year (1 every 4 months), for a total of 3 over the one year period including inspection, adjustment and servicing of the mechanical, electrical and other applicable component parts to ensure proper function. This includes inspecting control panel, air pumps, air filters, diffuser operation. Any alarm situation affecting the proper function of the Aerobic process will be addressed within a 48-hour time frame. Repair work on non-warranty parts will include price for parts & labor. The prices will be quoted before work is performed.
- 2. An effluent quality inspection consisting of a visual check for color, turbidity, scum overflow and examination for odors. A test for chlorine residual and PH will be taken and reported as necessary.
- 3. If any improper operation is observed, which cannot be corrected at the time of the service visit, you will be notified immediately in writing of the conditions and estimated date of correction.
- 4. The client is responsible for chlorine. Must be filled before or during the service visit.
- 5. Any additional visits, inspections or sample collection required by specific Municipalities, Water/River Authorities, County Agencies the TCEQ or any other authorized regulatory agency in your jurisdiction will be covered by this policy.

The property owner's manual must be strictly followed or warranties are subject to invalidation. Pumping of sludge build-up is not covered by this policy and will result in additional charges.

### **ACCESS BY CONTRACTOR**

The Contractor or anyone authorized by the Contractor may enter the property at reasonable times without prior notice for the purpose of the above described Services. The contractor may access the System components including the tanks by means of excavation for the purpose of evaluations if necessary. Soil is to be replaced with the excavated material as best as possible.

### <u>Termination of Agreement</u>

Either party may terminate this agreement within ten days written notice in the event of substantial failure to perform in accordance with its terms by the other party without fault of the terminating party. If this Agreement is so terminated, the Contractor will immediately notify the appropriate health authority of the termination.

### **Limit of Liability**

In no event shall the Contractor be liable for indirect, consequential, incidental or punitive damages, whether in contract tort or any other theory. In no event shall the Contractor's liability for direct damages exceed the price for the services described in this Agreement.

### **Dispute Resolution**

If a dispute between the Client and the Contractor arises that cannot be settled in good faith negotiations then the parties shall choose a mutually acceptable arbitrator and shall share the cost of the arbitration services equally.

### **Entire Agreement**

This Agreement contains the entire agreement of the parties, and there are no other promises or conditions in any other agreement either oral or written.

### **Severability**

If any provision of this Agreement shall be held to be invalid or unenforceable for any reason, the remaining provisions shall continue to be valid and enforceable. If a court finds that any provision of this agreement is invalid or unenforceable, but that by limiting such provision it would become valid and enforceable, then such provision shall be deemed to be written, construed, and enforced as so limited.

### **PLEASE REMIT** 370.00 **SERVICE PROVIDER Aerobic Services** 15188 FM 306 Canyon Lake, TX 78133 Customer Signature \*\*\*To pay online, proceed to the "Billing" Tom Hampton VP section in your Customer Portal License # OS0024597 / MP 349





Canyon Lake: (830) 964-2365 Bastrop: (512) 303-6922

info@aerobicservices.com bastrop@aerobicservices.com

MP349 / OS24597 www.aerobicservices.com

					WWW.doi.obioco.viocoi.com		
To:	Carrie West		Tech:	Nick			
1012 Road Runner L		n	——— Phone: (	210) 264-1617	Date: 2024-08-30		
-	Canyon Lake, TX 78	133	Alt Ph:		Service		
Agency:	Comal		<del></del>		Due:		
County:	Comal						
Permit No:	108167						
Inspection Type	<b>)</b> :						
<u>Item</u>		<u>Operational</u>	Inoperative	Not Prese	nt		
Aerator:		[X]	[]	[]	Air Pressure: 90		
Irrigation Pump	o:	[X]	[]	[]			
Air Compresso	r:	[X]	[]	[]			
Pump Screen:		[X]	[]	[]			
Chlorinator:		[X]	[]	[]			
Spray Field Ve	getation:	[X]	[]	[]			
Filters:		[X]	[]	[]			
Sprinkler / Drip	Backwash:	[X]	[]	[]			
Controls / Elec	tric Circuits:	[X]	[]	[]			
Test Results ar	nd Observations: (A	s Required					
rest nesuns un	id Observations. (A	3 ricquireu,		Mixed Liquo	r: all measurements in inches		
Chlorine Residua (ppm):	0.06			Aeration:	48		
Test Method:	Dpd			Sludge Le	evels		
BOD:				Clarifier:	0		
TSS:				Pump:	7		
Tank Lids Secure	ed: Yes [X] / NO []						
Pump Out Neede	ed: Yes [] / NO [X]						
Repairs Made	Yes [] / NO [X]						
now, sprayer still call our office to s protect the water	perational, one spray intact didn't need to	be replaced. Syste most likely within t	m has pretty high sl he next 4-8 months	udge level in p at least the pu	create such a bad green patch in yard ump tank not 8 inches yet but need to mp tank needs a pumpout soon to		
·							
Inspector:				Date	2024-08-30		

Tom Hampton, VP MP349/OS24597